

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004201/RWP3Q2**Date:** 19/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00019772201		
Claimant Vehicle No :	SMX6453G	Insured Vehicle No :	SMV2650R		
Date of Loss:	21/04/2023	Nature of Claim:	TP	Claim No:	SNM23D202935/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX6453G		
Make & Model:	CITROEN C4, 1.6 PICASSO (A)	Engine No:	10JBHD3051371
Reg. Date:	14/07/2016 (Man. Year: 2016)	Chassis No:	VF73ABHZTGJ658025
Colour:	White	Odometer:	98138 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,687.00	4,724.00	7,963.00	62.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,160.00	4,330.00	5,830.00	57.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,847.00	9,054.00	13,793.00	60.37
+ GST 8.00/8.00% (S\$)	1,827.76	724.32	1,103.44	60.37
Nett Amount (S\$)	24,674.76	9,778.32	14,896.44	60.37

INSPECTION

Date of Assignment:	24/04/2023	
Date Inspected:	09/05/2023 Inspected At:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS Singapore 609339
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	144	CITROEN C4 1.6 PICASSO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX6453G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY PNL SEALANT	Not Necessary	80.00 FS	*- FS
2	1		*RR NUMBER PLATE WITH CASING	Cracked	80.00 FS	*80.00 FS
3	1		*BODY PNL SEALANT	Not Necessary	100.00 FS	*- FS
4	1		*C&C BADGE	Necessary	80.00 FS	*80.00 FS
5	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS
6	1		*REAR BUMPER	Cracked	1,634.00 FS	*1,634.00 FS
7	1		*BUMPER BRACKET	Not Necessary	355.00 FS	*- FS
8	1		*BUMPER SKIRT	Deformed	539.00 FS	*539.00 FS
9	1		*SET BRACKET	Deformed	233.00 FS	*233.00 FS
10	1		*BRACKET SET LAT	Not Necessary	233.00 FS	*- FS
11	1		*BUMPER BRACKET	Deformed	491.00 FS	*491.00 FS
12	1		*STIFFENER LH	Not Necessary	220.00 FS	*- FS
13	1		*STIFFENER RH	Not Necessary	220.00 FS	*- FS
14	1		*LOW RR PAN FIX	Not Necessary	223.00 FS	*- FS
15	1		*SENSOR SUPPORT	Not Necessary	269.00 FS	*- FS
16	1		*REAR PANEL ASS	Not Necessary	884.00 FS	*- FS
17	1		*TAILGATE	Not Necessary	2,988.00 FS	*- FS
18	1		*TLGT EXT PANEL	Cracked	569.00 FS	*569.00 FS
19	1		*WEATHERSTRIP	Not Necessary	212.00 FS	*- FS
20	1		*SPOILER LH	Not Necessary	231.00 FS	*- FS
21	1		*SPOILER RH	Not Necessary	231.00 FS	*- FS
22	1		*BADGE -C4	Necessary	91.00 FS	*91.00 FS
23	1		*BADGE -PICASSO	Necessary	91.00 FS	*91.00 FS
24	1		*BADGE -LOGO	Necessary	114.00 FS	*114.00 FS
25	1		*BADGE -BLUEHDI	Necessary	91.00 FS	*91.00 FS
26	1		*TAIL-LIGHT LH COMPLEMENTAIE	Not Necessary	199.00 FS	*- FS
27	1		*TAIL-LIGHT RH COMPLEMENTAIE	Not Necessary	224.00 FS	*- FS
28	2		*SENSOR -CTR	Not Necessary	456.00 FS	*- FS
29	2		*SENSOR -CTR	Not Necessary	778.00 FS	*- FS
30	1		*BUMPER BRACKET	Deformed	691.00 FS	*691.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	12,687.00	4,724.00
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW TAILGATE ,TAILGATE LWR PNL RR BUMPER & RR END PNL	New	4,560.00	1,520.00
2	RESPRAY TAILGATE ,TAILGATE LWR PNL ,RR BUMPER & RR END PNL	New	2,750.00	1,100.00
3	REMOVE & REFIT TAILGATE COMPONENT	New	380.00	0.00
4	REMOVE & REFIT RR FLR BOARD ,TRIM & CARPET	New	380.00	180.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	100.00	100.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	380.00	380.00
7	REMOVE & REFIT RR WS GLASS	New	380.00	0.00
8	REMOVE & REFIT REVERSE SENSOR	New	120.00	120.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	180.00	0.00
10	REPAIR REAR END PANEL	New	380.00	380.00
11	RESPRAY REAR END PANEL	New	550.00	550.00
Gross Labour Cost (S\$)			10,160.00	4,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >