



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|---|--|
| LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428 | | | Ref: CS/LIP23004228/Uny3m4 Date: 05/05/2023 Code: LIP | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SLG 4212A | Veh. Inspected | GBL 3951Z | |
| Policy No. | SD21V12191 | Coverage (\$) | 0.00 | |
| Claim No. | AVS23/1207 | Excess (\$) | 0.00 | |
| Assign From | ANDY SEAH | Assign Date | 25/04/2023 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA HIACE (A) | c.c | 2982 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | JTFHT02P100251962 | Colour | WHITE | |
| Odometer | 36067 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195 R15 | TRIANGLE | 6 mm | |
| L/H Front Tyre | 195 R15 | TRIANGLE | 6 mm | |
| R/H Rear Tyre | 195 R15 | TRIANGLE | 6 mm | |
| L/H Rear Tyre | 195 R15 | TRIANGLE | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 11/04/2023 | Inspection Date | 25/04/2023 | |
| Survey held at | FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840 | | | |
| 5a. Remarks | | | | |
| A)REGISTRATION DATE: 01 JUL 2021 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 3 Working Days | |