

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1364T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER SIDE BRACKETS LH	SERVICEABLE	55.80	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REFLECTOR LAMP LH	SERVICEABLE	41.45	-
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
	LESS 20% DISCOUNT		-225.74	-186.53
			902.96	746.12
	NETT ITEMS			
1	REVERSE SENSORS (N)	SERVICEABLE	180.00	-
	LESS 10% DISCOUNT		-18.00	-
			162.00	-
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			820.00	630.00
	GRAND TOTAL		1,934.96	1,426.12
	RECOMMENDED COST OF LUMP SUM REPAIRS			1,150.00

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC23004229/Nwp3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser