

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SH 8548S Yr Regn: 2016 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i40 1.7 CRDI c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 1084466 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM4LB41UM4U089884

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WATSLAKE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 19/04/23Survey held at COMFORTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis/frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_  
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

2) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos

Others

Report Format : \_\_\_\_\_

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

TOTAL

## COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 19.04.2023

SJJ2036M

MODEL: Hyundai i40INSURANCE: INCOME (45)VEHICLE NO.: SH 8548SMVA: LIM T S

| PART NO. | DESCRIPTION                            | QTY | UNIT PRICE | AMOUNT                   |
|----------|----------------------------------------|-----|------------|--------------------------|
|          | Rear Bumper <i>de</i>                  | 1   |            | \$ 553.00                |
|          | Rear Bumper Under Cover <i>sea</i>     | 1   |            | \$ 228.00                |
|          | Rear Bumper Reinforcement ?            | 1   |            | \$ 428.40                |
|          | Rear Bumper Reinforcement Brkt RH/LH ? | 2   | \$ 80.40   | \$ 160.60                |
|          | Rear Bumper Clips <i>ne</i>            | 10  | \$ 2.20    | \$ 22.00                 |
|          | <b>SUB TOTAL</b>                       |     |            | \$ 1,392.00              |
|          | <b>LESS 20%</b>                        |     |            | \$ 278.40                |
|          | <b>DISCOUNTED TOTAL</b>                |     |            | \$ 1,113.60              |
|          | Reverse Sensors <i>X</i>               | 1   |            | \$ 135.70 <i>X</i>       |
|          | <b>LESS 10%</b>                        |     |            | \$ 13.57                 |
|          | <b>S/NETT TOTAL</b>                    |     |            | \$ 122.13                |
|          | Rear Bumper Mat <i>ne</i>              | 1   |            | \$ 50.00 <b>NETT</b>     |
|          | <b>SPARE PARTS TOTAL</b>               |     |            | \$ 1,285.76              |
|          | <u>Labour Charge</u>                   |     |            |                          |
|          | Panel Beating                          |     |            | \$ 280 <del>300.00</del> |
|          | Spray Painting Charge                  |     |            | \$ 250 <del>300.00</del> |
|          | R/I Reverse Sensors                    |     |            | \$ 46 <del>120.00</del>  |
|          | <b>TOTAL LABOUR</b>                    |     |            | \$ 720.00                |
|          | <b>ESTIMATE TOTAL</b>                  |     |            | \$ 2,005.73              |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rare*  
*Hp 90010068*  
*3 days*  
*45*  
*12/04/23 P1110*  
*Rare after repair*

Date/Time: 19.04.2023 08:25 Page : 1

ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 5893555

JC NO305551546

|                                                                                                                             |                                          |                                         |
|-----------------------------------------------------------------------------------------------------------------------------|------------------------------------------|-----------------------------------------|
| COMFORT TRANSPORTATION PTE LTD<br>7010045<br>383 SIN MING DRIVE<br>Singapore SINGAPORE 575717<br>65508755<br>(R) (O)<br>(P) | REGN NO:<br><b>SH 8548S</b>              | MILEAGE                                 |
|                                                                                                                             | MAKE:<br><b>HYUNDAI</b>                  | FUEL<br>E.....1/2.....F                 |
|                                                                                                                             | MODEL<br><b>I-40</b>                     | DATE/TIME IN<br><b>17.04.2023 17:15</b> |
|                                                                                                                             | YR OF MANU<br><b>25.05.2016</b>          | TARGET DATE                             |
|                                                                                                                             | CHASSIS CODE<br><b>KMHLB41UMGU089894</b> | COMPLETION DATE/TIME:                   |


JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 17.04.2023  
 TURE: 3P 17.04.2023

NO LABOR CODE  
 0010 PB

DESCRIPTION  
 PANEL BEATING-SH 8548S-TP



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Adgement Slip

Exit Pass

lo.: SH 8548S LIMTS

Vehicle No.: SH 8548S

Service Advisor

Signature/Date

Name of Service Advisor

Date

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

821R

### Vehicle Details

Vehicle No.:

SH85485

Vehicle to be Exported:

No

Intended Deregistration Date:

24 Apr 2023

Vehicle Make:

HYUNDAI

Vehicle Model:

I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Primary Colour:

Blue

Manufacturing Year:

2016

Engine No.:

D4FDFU562081

Chassis No.:

KMHLB41UMGU089894

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$20,070.00

Original Registration Date:

26 May 2016

First Registration Date:

26 May 2016

Transfer Count:

0

Actual ARF Paid:

\$20,098.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

25 May 2024

PARF Rebate Amount:

\$13,063.00

### Intended COE Rebate Details

COE Expiry Date:

25 May 2024

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$36,463.00

COE Rebate Amount:

\$4,949.00

Total Rebate Amount:

\$18,012.00