

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC23004240/Rqp3e2	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	18-05-2023 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMH 4826L	Veh. Ir	spected	SH 9076E
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1219276-002	Exces	s (\$)	0.00
	Assign From		Assign	n Date	19/04/2023
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ 1.6 DCT	C.C		1580
	Engine No.	HIDDEN	Year o	f Reg.	2019
	Chassis No.	KMHC851CVKU164267	Colou	•	BLUE
	Odometer	481936	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST		6 mm
	L/H Front Tyre	195/65 R15	WEST		6 mm
	R/H Rear Tyre	195/65 R15	WEST I	_AKE	6 mm
	L/H Rear Tyre	195/65 R15	WEST I	_AKE	6 mm
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/04/2023	Inspec	tion Date	19/04/2023
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				