

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8262Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	481.10	481.10
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER UPPER MOULDING	SCRATCHED	368.50	368.50
1	FRONT BUMPER SPONGE	NOT NECESSARY	186.90	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	1,136.70	-
1	FRONT BUMPER LOWER GRILLE	SCRATCHED	368.50	368.50
1	FRONT BUMPER LOWER MOULDING	SCRATCHED	187.20	187.20
1	RADIATOR GRILLE	CRACKED	1,409.10	1,409.10
1	HEADLAMP LH	NOT NECESSARY	2,110.30	-
1	DAYLIGHT LH	NOT NECESSARY	642.50	-
1	DAYLIGHT GRILLE LH	NOT NECESSARY	93.45	-
	LESS 20% DISCOUNT		-1,401.25	-567.28
			5,605.00	2,269.12
	NETT ITEMS			
1	FRONT NO.PLATE WITH TRIM COVER (N)	NECESSARY	55.00	55.00
	LESS 10% DISCOUNT		-5.50	-5.50
			49.50	49.50
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING.		300.00	250.00
	TUFF KOTE.	NOT NECESSARY	40.00	-
	CHECK LIGHTINGS/WIRINGS.		40.00	30.00
			780.00	630.00
	GRAND TOTAL		6,434.50	2,948.62





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		2,948.62
(CONFIRMED)		

Report Ref No. NS/INC23004242/Rnp3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser