

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC23004242/Rnp3m4	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	08-05-2023 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBE 8992J	Veh. Ir	spected	SHC 8262Y
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1219846-002	Exces	s (\$)	0.00
	Assign From		Assign	n Date	19/04/2023
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ 1.6 DCT	C.C		1580
	Engine No.	HIDDEN	Year o	f Reg.	2021
	Chassis No.	KMHC851CVLU193068	Colou	•	BLUE
	Odometer	221625	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65R15	WEST		6 mm
	L/H Front Tyre	195/65R15	WEST		6 mm
	R/H Rear Tyre	195/65R15	WEST I	_AKE	6 mm
	L/H Rear Tyre	195/65R15	WEST I	_AKE	6 mm
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/04/2023	Inspection Date 19/04/2023		
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969				
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				