

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 6489T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	GRAZED / DEFORMED	541.20	541.20
2	FRONT BUMPER SIDE RETAINER LH/RH @\$181.90	NOT NECESSARY	363.80	-
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	231.45	-
1	FRONT BUMPER UNDERCOVER	NOT NECESSARY	571.75	-
1	FRONT PANEL	NOT NECESSARY	1,020.25	-
1	FRONT PANEL MIDDLE	NOT NECESSARY	731.10	-
1	FRONT PANEL BOTTOM	NOT NECESSARY	781.25	-
1	FRONT HEADLAMP LH	SCRATCHED / CRACKED	2,584.10	2,584.10
1	FOG LAMP LH	NOT NECESSARY	371.10	-
1	FOG LAMP COVER LH	SCRATCHED	121.25	121.25
1	FRONT DOOR PILLAR	NOT NECESSARY	631.10	-
1	FRONT DOOR LH	NOT NECESSARY	1,887.10	-
	LESS 25% DISCOUNT		-2,458.86	-811.64
			7,376.59	2,434.91
	SPECIAL NETT ITEMS			
8	FRONT BUMPER CLIPS @\$5.50 (SN)	NECESSARY	44.00	40.00
8	FRONT GRILLE CLIP @\$5.50 (SN)	NOT NECESSARY	44.00	-
			88.00	40.00
	<u>LABOUR</u>			
	TO CHECKING ELECTRICAL WIRING AND CHECK FUNCTIONS.		60.00	20.00
	TO RESPRAY UNDERCOATING /RUST PROOFING.	NOT NECESSARY	120.00	-
	TO RESPRAY PAINTING & ETC.	NOT NECESSARY	800.00	-
	PANEL BEATING ,CUT ,WELD ,REMOVE AND REPLACING ABOVE PARTS .		800.00	260.00
			1,780.00	280.00
	GRAND TOTAL		9,244.59	2,754.91

Report Ref No. CS/SMO23004248/Uvy3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,200.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMO23004248/Uvy3q2

CHUA KANG SENG

**Licensed Appraiser**