



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23004248/Uvy3q2	
			Date: 15/05/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMV 4306Y	Veh. Inspected	GBH 6489T
	Policy No.	D22MTPV01014795	Coverage (\$)	0.00
	Claim No.	CMTD2301607/GPL	Excess (\$)	0.00
	Assign From	GRACE NG	Assign Date	25/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE (A)	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GDH2012001887	Colour	SILVER
	Odometer	125549 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195 R15	TOYO	6 mm
	L/H Rear Tyre	195 R15	TOYO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/04/2023	Inspection Date	27/04/2023
	Survey held at	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	