

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	MS FIRST CAPITA	L INSURANCE LTD	R	Ref:	CS3/FCI23004250/Rqy3e2	
	16 RAFFLES QUAY #42-01 HONG LEC SINGAPORE 0485	NG BUILDING	D	Date:	28/07/2023	
			C	Code:	FCI2	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YP 3894L	Veh. Inspected		SMG 4445H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D23001392MFCV	Excess (\$)		0.00	
	Assign From	CAROLINE CABRERA	Assign Date		25/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI ATTRAGE 1.2 CVT	c.c		1193	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MMBSTA13AJH004374	Colour		RED	
	Odometer	28143 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/55 R15	TOURADOR		6 mm	
	L/H Front Tyre	185/55 R15	TOURADOR		6 mm	
	R/H Rear Tyre	185/55 R15	TOURADOR		6 mm	
	L/H Rear Tyre	185/55 R15	TOURADOR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	LE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	20/04/2023	Inspect Date / Ti	me	25/04/2023 (03:58 PM)	
	Survey held at	Survey held at GOLD AUTOWORKS PTE LTD				
	48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$65,000.00					

Report Ref No. CS3/FCI23004250/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser