

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23004253/AVY3Q2**Date:** 24/05/2023**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP321091
Claimant Vehicle No :	SJX6070M	Insured Vehicle No :	SLU1874K
Date of Loss:	21/04/2023	Nature of Claim:	TP
		Claim No:	MPC04105

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX6070M		
Make & Model:	KIA CERATO FORTE, 1.6 (A)	Engine No:	G4FCAH387900
Reg. Date:	28/06/2010 (Man. Year: 2010)	Chassis No:	KNAFU411MA5230745
Colour:	Black	Odometer:	430995 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,682.43	3,089.51	2,592.92	45.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	1,690.00	1,600.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,972.43	4,779.51	4,192.92	46.73
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	8,972.43	3,800.00	5,172.43	57.65

INSPECTION

Date of Assignment:	25/04/2023		SIN YU SIN WORKSHOP
Date Inspected:	26/04/2023	Inspected At:	1 KAKI BUKIT AVE 6
			#01-82 AUTOBAY
			SINGAPORE 417883
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2023)
Parts:	144	KIA CERATO FORTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX6070M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	688.50 FL	*688.50 FL
2	1		*FRONT BUMPER SIDE HOLDER	Damaged	27.60 FL	*27.60 FL
3	1		*FRONT BUMPER FOG LAMP	Not Necessary	202.70 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	86.20 FL	*- FL
5	1		*HEADLAMP	Cracked	498.80 FL	*498.80 FL
6	1		*HEADLAMP LOWER ARM	Bent	36.30 FL	*36.30 FL
7	1		*FRONT FENDER	Dirt	569.90 FL	*569.90 FL
8	1		*FRONT FENDER INNER SHIELD	Not Necessary	127.90 FL	*- FL
9	1		*BONNET	Dented	873.20 FL	*873.20 FL
10	1		*FRONT SUPPORT PANEL	Cracked	649.60 FL	*649.60 FL
11	1		*FRONT LOWER ARM	Not Necessary	374.90 FL	*- FL
12	1		*FRONT SHOCK ABSORBER	Not Necessary	338.40 FL	*- FL
13	1		*FRONT KNUCKLE ARM	Not Necessary	387.90 FL	*- FL
14	1		*FRONT WHEEL HUB C/W BEARING	Not Necessary	240.80 FL	*- FL
15	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
16	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
17	1		*COOLANT	Necessary	50.00 FS	*50.00 FS
18	1		*FRONT WHEEL RIM	Not Necessary	700.00 FS	*- FS
19	1		*FRONT TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,192.70	3,423.90
- List Item Discount on L Items 10.00/10.00% (S\$)	510.27	334.39
Total Parts (S\$)	5,682.43	3,089.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVE AND REFIT PARTS	New	1,400.00	900.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	600.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	40.00
5	TO REMOVE CONDENSER & TO TOP UP A/C GAS	New	120.00	60.00
6	TO REMOVE RADIATOR & TOP UP COOLANT	New	120.00	60.00
7	TO REMOVE FRONT UNDERCARRIAGE	New	300.00	0.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (S\$)			3,290.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >