

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23004272/CVP3E2**Date:** 12/05/2023**REFERENCE**

Insured/Claimant:	CHARMAINE ONG JING WEN	Policy No:	SP2002843919-01
Date of Loss:	21/04/2023	Nature of Claim:	OD
		Claim No:	202332007521

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT2640R		
Make & Model:	KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)	Engine No:	G4FC9H286623
Reg. Date:	30/09/2009 (Man. Year: 2009)	Chassis No:	KNAFW411MA5116194
Colour:	Silver	Odometer:	153026 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$12,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	5 mm	Rear Left Side:	5 mm
Front Right Side:	5 mm	Rear Right Side:	5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,840.65	3,069.55	771.10	20.08
Miscellaneous Items	110.00	100.00	10.00	9.09
Labour	3,690.00	1,480.00	2,210.00	59.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,640.65	4,649.55	2,991.10	39.15
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	7,640.65	3,250.00	4,390.65	57.46
+ GST 8.00/8.00% (S\$)	611.25	260.00	351.25	57.46
Nett Amount (S\$)	8,251.90	3,510.00	4,741.90	57.46

INSPECTION

Date of Assignment:	25/04/2023	Present Location:	Chia Auto Services Pte Ltd (HQ)
Date Inspected:	26/04/2023	Inspected At:	Chia Auto Services Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Vicom Inspection Center Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: SIMON HO LEONG CHUAN**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2023)
Parts:	143	KIA CERATO FORTE 1.6 SX AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT2640R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Buckled	380.00 F	*380.00 F
2	2		*BONNET HINGE (WCP)	Not Necessary	70.00 F	*- F
3	1		*BONNET CENTRE RUBBER (WCP)	Bent	30.00 F	*30.00 F
4	1		*BONNET LOCK (WCP)	Bent	85.00 F	*85.00 F
5	1		*FRONT BUMPER (WCP)	Deformed	280.00 F	*280.00 F
6	2		*FRONT BUMPER SIDE RETAINER (WCP)	Not Necessary	56.00 F	*- F
7	1		*FRONT BUMPER LOWER CENTRE GRILLE (WCP)	Cracked	90.00 F	*90.00 F
8	2		*FRONT BUMPER FOGLAMP (WCP)	Not Necessary	240.00 F	*- F
9	2		*FRONT BUMPER FOGLAMP HOUSING (WCP)	Not Necessary	160.00 F	*- F
10	1		*FRONT BUMPER SPONGE (WCP)	Cracked	90.00 F	*90.00 F
11	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	180.00 F	*180.00 F
12	1		*FRONT BUMPER NUMBER PLATE GARNISH (WCP)	Cracked	70.00 F	*70.00 F
13	1		*FRONT CENTRE GRILLE (WCP)	Cracked	180.00 F	*180.00 F
14	1		*FRONT CENTRE GRILLE LOGO (WCP)	Necessary	60.00 F	*60.00 F
15	2		*HEADLAMP (WCP)	Cracked	560.00 F	*560.00 F
16	1		*FRONT FENDER (WCP)	O/S Bent / N/S Repair	440.00 F	*220.00 F
17	1		*FRONT SUPPORT PANEL (WCP)	Cracked	420.50 F	*420.50 F
18	1		*HORN (2PCS)(WCP)	Dented (1Pc Only)	100.00 F	*50.00 F
19	2		*HEADLAMP LOWER BRACKET (WCP)	Bent	-	*60.00 F
20	1		*AIRCON CONDENSOR SIDE GUIDE RH (WCP)	Distorted	-	*35.00 F

F=Franchise part.

Sub Total (S\$)	3,491.50	2,790.50
+ Margin on L,N Items 10.00/10.00% (S\$)	349.15	279.05
Total Parts (S\$)	3,840.65	3,069.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BONNET RUBBER CLIPS (SET) (NECESSARY)	20.00	20.00
2	1	CENTRE GRILLE CLIPS (SET) (NECESSARY)	20.00	20.00
3	1	FRONT BUMPER CLIPS (SET) (NECESSARY)	20.00	20.00
4	1	FRONT NUMBER PLATE WITH HOLDER (MISSING/CRACKED)	50.00	40.00
Sub Total (\$\$)			110.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	50.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSER AND TOP UP GAS	New	100.00	0.00
6	REMOVE AND REFIX RADIATOR AND CONDUST PRESSURE TEST	New	60.00	0.00
Gross Labour Cost (\$\$)			3,690.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >