

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23004275/RNY3E2**Date:** 06/07/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP309030
Claimant Vehicle No :	SMG4842U	Insured Vehicle No :	SFC8099B
Date of Loss:	21/04/2023	Nature of Claim:	TP
		Claim No:	MPC04110

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG4842U	Engine No:	G4FGJH713226
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF1416MK5024511
Reg. Date:	21/12/2018 (Man. Year: 2018)	Odometer:	119586 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,431.00	3,263.00	4,168.00	56.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,380.00	4,450.00	3,930.00	46.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,811.00	7,713.00	8,098.00	51.22
+ GST 8.00/8.00% (S\$)	1,264.88	617.04	647.84	51.22
Nett Amount (S\$)	17,075.88	8,330.04	8,745.84	51.22

INSPECTION

Date of Assignment:	25/04/2023	
Date Inspected:	22/05/2023	Inspected At: Cycle & Carriage Automotive Pte Ltd 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG4842U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR NUMBER PLATE WITH CASING	Not Necessary	80.00 FS	*- FS
2	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
3	1		*BODY PNL SEAANT	Necessary	80.00 FS	*80.00 FS
4	1		*C&C BADGE	Necessary	80.00 FS	*50.00 FS
5	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
6	1		*COVER-RR BUMPER	Deformed	749.00 FS	*749.00 FS
7	1		*COVER-RR BUMPER LWR	Deformed	241.00 FS	*241.00 FS
8	1		*COVER-RR BUMPER UNDER, LH	Not Necessary	33.00 FS	*- FS
9	1		*COVER-RR BUMPER FOG LAMP, LH	Not Necessary	19.00 FS	*- FS
10	1		*COVER-RR BUMPER FOG LAMP, RH	Cut	19.00 FS	*19.00 FS
11	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	201.00 FS	*- FS
12	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	201.00 FS	*- FS
13	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FS	*- FS
14	1		*BEAM-RR BUMPER	Cracked	318.00 FS	*318.00 FS
15	1		*STAY-RR BUMPER LH	Not Necessary	65.00 FS	*- FS
16	1		*STAY-RR BUMPER RH	Not Necessary	65.00 FS	*- FS
17	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FS	*- FS
18	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FS	*- FS
19	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	6.00 FS	*- FS
20	2		*BRACKET-RR BEAM LWR MTG	Not Necessary	12.00 FS	*- FS
21	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FS	*- FS
22	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Not Necessary	31.00 FS	*- FS
23	1		*PANEL ASSY-TRUNK LID	Bent	1,566.00 FS	*1,566.00 FS
24	1		*HINGE ASSY-TRUNK LID, LH	Not Necessary	107.00 FS	*- FS
25	1		*HINGE ASSY-TRUNK LID, RH	Not Necessary	97.00 FS	*- FS
26	1		*PANEL ASSY-BACK	Not Necessary	324.00 FS	*- FS
27	1		*W/STRIP-TRUNK LID OPNG	Necessary	100.00 FS	*100.00 FS
28	1		*LATCH ASSY-TRUNK LID	Not Necessary	112.00 FS	*- FS
29	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FS	*32.00 FS
30	1		*EMBLEM-CERATO	Necessary	28.00 FS	*28.00 FS
31	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 FS	*- FS
32	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	638.00 FS	*- FS
33	1		*LAMP ASSY-REAR COMB INSIDE, LH	Not Necessary	346.00 FS	*- FS
34	1		*LAMP ASSY-REAR COMB INSIDE, RH	Not Necessary	346.00 FS	*- FS
35	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Not Necessary	402.00 FS	*- FS
36	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Not Necessary	402.00 FS	*- FS
37	1		*REAR LICENSE PLATE WITH PLASTIC FRAME	Scratched	50.00 FS	*50.00 FS
38	10		*CLIPS	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **7,431.00** **3,263.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER, RR END PNL & BOOTLID. REPAIR RR FLR PNL, LHR FENDER & RHR FENDER	New	3,840.00	1,920.00
2	RESPRAY RR BUMPER, RR END PNL, BOOTLID RR FLR PNL, LHR FENDER & RHR FENDER	New	3,300.00	1,650.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	280.00	280.00
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET	New	280.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	100.00	100.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
7	REMOVE & REFIT REVERSE SENSOR	New	120.00	120.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	180.00	100.00
Gross Labour Cost (\$\$)			8,380.00	4,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >