


(08/11/13) wef  
ASS. REC. BY: Marcus

REF: CC4/HSB23004281/Upa3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD (TP) WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: GBC 2935D  
at Workshop m/s 7LM  
of \_\_\_\_\_  
Insured: SHA 8568B  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: 855k  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 4 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS C 433d  
Date: \_\_\_\_\_ Person Contacted: LIA 15445  
Vehicle: IN / OUT

Veh No: GBC 2935D Yr Regn: 12/07/17  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or (M)  
Make: Zyote Dyno c.c 2982  
Colour: silver A/C: Insured / Std / NI / NA  
Sp.Reading: 183514 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: KDY 231802 7988  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Order / Jammed / Leaked / Burnt or  
Brake: Order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 195 R15  
R: 165 R13  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or 1209 sen  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6/6 mm  
L/Bal. 6 mm L/Bal. 6/6 mm  
D.O.A. 20/04/23 D.O.I. 4/5/23  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/5/23	4/5 @ 2100 informed MR Tan

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

1) Date/Time, File Return to?  
2) \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$) \_\_\_\_\_ )

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	

**TLM Automobile Pte Ltd**

**1 Defu Lane 6 Singapore 539365**

**UEN number: 202244624K**

Messrs Bescon Equipment Pte Ltd

Estimate To Repair

GBG2935D - TOYOTA DYNA 3.0M

Chassis No : KDY2318027988

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Third Party Insurer : HSBC Life

Date of accident : 20.04.2023

Date: 25.04.2023

Not Allowed  
4/5/23  
2/5 \$2100

H. Jeyaraj  
TLM Automobile Pte Ltd

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
1	1 pc	tailgate lid <i>R</i>	\$ 1,037.20 <i>X</i>
2	1 pc	tailgate lid TOYOTA sticker <i>NF</i>	\$ 222.40 <i>X</i>
3	1 pc	tailgate lid lock latch <i>NLS</i> <i>Sub/turn</i>	\$ 60.60 <i>✓</i>
4	2 pc	tailgate hinge - circlip pin @ \$5.50 <i>NA</i>	\$ 22.00 <i>X</i>
5	1 pc	tailgate step metal <i>Sub</i>	\$ 80.00 <i>✓</i>
6	1 pc	rear cargo dock end panel <i>Sub</i>	\$ 488.10 <i>✓</i>
7	2 pc	side gate lid lock latch @ \$66.10 <i>repair</i>	\$ 132.20 <i>X</i>
8	2 pc	side gate lid lock handle @ \$68.20 <i>NA</i>	\$ 136.40 <i>X</i>
9	1 pc	side gate lid lock rubber stopper <i>NLS</i>	\$ 57.40 <i>✓</i>
10	1 pc	side gate lid lock rubber stopper angle bracket <i>NLS</i> <i>Sub</i> <i>70.00</i>	\$ 50.00 <i>✓</i>
11	1 pc	rear number plate bracket <i>Sub</i>	\$ 74.20 <i>✓</i>
12	2 pc	rear number plate lamp @ \$28.50 <i>NA</i>	\$ 57.00 <i>X</i>
13	2 pc	rear lamp @ \$309.80 <i>NLS one o/s one n/c</i>	\$ 619.60 <i>X</i>
14	2 pc	rear lamp bracket @ \$51.80 <i>NLS Sub o/s NA</i>	\$ 103.60 <i>X</i>
15	1 pc	spare tyre holder <i>NA</i>	\$ 252.20 <i>X</i>
16	1 pc	rear silencer pipe <i>NA</i>	\$ 300.00 <i>X</i>
			\$ 3,692.90
Less 20% GST			\$ 738.58
			\$ 2,954.32
<b>SPECIAL NETT ITEMS</b>			
17	1 pc	tailgate "70kh/h" sticker <i>NA</i>	\$ 20.00 <i>100</i>
18	1 pc	tailgate "DYNA" sticker <i>NA</i>	\$ 25.00 <i>✓</i>
19	1 pc	tailgate "1500kg" sticker <i>NA</i>	\$ 20.00 <i>X</i>
20	1 pc	spare tyre <i>NA</i>	\$ 120.00 <i>X</i>
21	1 pc	spare tyre rim <i>NA</i>	\$ 120.00 <i>X</i>
22	1 pc	rear number plate <i>one</i>	\$ 50.00 <i>20</i>
23	1 pc	rear reserve sensor <i>no/Reserve</i>	\$ 200.00 <i>✓</i>
24	1 pc	rear tools box <i>DD/Sub</i>	\$ 300.00 <i>✓</i>
			\$ 855.00
<b>LABOUR &amp; MISC. CHARGES</b>			
1		To rust-proofing of the affected areas.	\$ 80.00 <i>30</i>
2		To transfer of tailgate fittings, attachments and perform water seepage test.	\$ 110.00 <i>X</i>
4		To check electrical lighting concerned.	\$ 80.00 <i>20</i>
5		Putty and spray painting of the affected portion.	\$ 600.00 <i>580</i>
6		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00 <i>✓</i>
			\$ 1,460.00
<b>Grand Total</b>			\$ 5,269.32

2-1171.9  
252  
878.92  
2663.12