

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23004290/TVP3E2  
**Date:** 31/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00012212301
<b>Claimant Vehicle No :</b>	GBG20G	<b>Insured Vehicle No :</b>	GBJ9339M
Date of Loss:	20/04/2023	Nature of Claim:	TP
		Claim No:	SNM23D202942/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBG20G</b>		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (M)	Engine No:	ZD30016747N
Reg. Date:	19/05/2017 (Man. Year: 2016)	Chassis No:	JN1SC2F24Z0859396
Colour:	Silver	Odometer:	215570 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6/6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	28,497.82	4,315.06	24,182.76	84.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	1,400.00	4,600.00	76.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>34,497.82</b>	<b>5,715.06</b>	<b>28,782.76</b>	<b>83.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,550.00</b>		
<b>Nett Amount (S\$)</b>	<b>34,497.82</b>	<b>4,550.00</b>	<b>29,947.82</b>	<b>86.81</b>

INSPECTION

Date of Assignment:	26/04/2023		
Date Inspected:	28/04/2023	Inspected At:	MCR MOTORS PTE LTD (HQ) 8 Kaki Bukit Ave 4 #01-53 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 31 May 2023)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG20G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,688.40 FL	*1,399.00 FL
2	1		*REAR TAILGATE NISSAN STICKER	Necessary	254.90 FL	*175.00 FL
3	1		*REAR TAILGATE HINGE CENTRE	Necessary	92.50 FL	*92.50 FL
4	1		*REAR TAILGATE HINGE RH	Not Necessary	92.50 FL	*- FL
5	1		*REAR TAILGATE SIDE LATCH RH	Not Necessary	166.35 FL	*- FL
6	1		*REAR TAILGATE SIDE LATCH LH	Bent	166.35 FL	*166.35 FL
7	1		*REAR TAILGATE STOPPER BRACKET RH	Not Necessary	197.60 FL	*- FL
8	1		*REAR TAILGATE STOPPER BRACKET LH	Not Necessary	197.60 FL	*- FL
9	2		*REAR TAILGATE STOPPER RUBBER RH	Not Necessary	87.60 FL	*- FL
10	2		*REAR TAILGATE STOPPER RUBBER LH	Not Necessary	87.60 FL	*- FL
11	1		*REAR TAILGATE LOWER PANEL (END PANEL)	Repair	625.00 FL	*- FL
12	1		*REAR TAILLAMP ASSEMBLY RH	Cracked	311.40 FL	*248.00 FL
13	1		*REAR TAILLAMP PANEL RH	Not Necessary	227.50 FL	*- FL
14	1		*REAR TAILLAMP ASSEMBLY LH	Cracked	311.40 FL	*248.00 FL
15	1		*REAR TAILLAMP PANEL LH	Repair	227.50 FL	*- FL
16	1		*REAR NUMBER PLATE BRACKET	Not Necessary	243.80 FL	*- FL
17	1		*REAR NUMBER PLATE LAMP	Not Necessary	114.30 FL	*- FL
18	1		*SPARE TYRE CARRIER	Not Necessary	357.50 FL	*- FL
19	1		*REAR EXHAUST PIPE	Not Necessary	753.80 FL	*- FL
20	1		*REAR EXHAUST BRACKET	Not Necessary	64.30 FL	*- FL
21	1		*REAR SIDE GATE RH	Not Necessary	1,887.20 FL	*- FL
22	1		*REAR SIDE GATE LH	Bent	1,887.20 FL	*1,699.00 FL
23	1		*REAR SIDE GATE LOWER PANEL RH	Not Necessary	799.00 FL	*- FL
24	1		*REAR SIDE GATE LOWER PANEL LH	Not Necessary	799.00 FL	*- FL
25	1		*REAR MUDGUARD RH	Not Necessary	316.50 FL	*- FL
26	1		*REAR MUDGUARD LH	Not Necessary	316.50 FL	*- FL
27	1		*REAR CHASSIS CROSSMEMBER	Not Necessary	854.00 FL	*- FL
28	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
29	1		*REAR REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
30	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
31	1		*REAR TAILGATE 70KM/H STICKER	Necessary	50.00 FS	*30.00 FS
32	1		*REAR TAILGATE 13PAX STICKER	Necessary	50.00 FS	*30.00 FS
33	1		*REAR TAILGATE ALUMINIUM PLATE	Not Necessary	1,200.00 FS	*- FS
34	1		*REAR SIDE GATE TOP STAINLESS STEEL RAILING RH	Not Necessary	1,500.00 FS	*- FS
35	1		*REAR SIDE GATE TOP STAINLESS STEEL RAILING LH	Not Necessary	1,500.00 FS	*- FS
36	1		*REAR SIDE GATE ALUMINIUM PLATE RH	Not Necessary	1,800.00 FS	*- FS
37	1		*REAR SIDE GATE ALUMINIUM PLATE LH	Not Necessary	1,800.00 FS	*- FS
38	1		*REAR FLOOR PANEL ALUMINIUM PLATE	Not Necessary	3,000.00 FS	*- FS
39	1		*REAR CANOPY	Not Necessary	3,500.00 FS	*- FS
40	1		*REAR STEP BRACKET	Bent	800.00 FS	*400.00 FS
41	1		*REAR TAILGATE LOWER PANEL (END PANEL) SEALANT	Not Necessary	150.00 FS	*- FS
42	1		*REAR SIDEGATE SEALANT RH	Not Necessary	150.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
43	1		*REAR SIDEGATE SEALANT LH	Not Necessary	150.00 FS	*- FS	
44	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS	
45	1		*REAR TAILGATE HINGE LH	Not Necessary	92.50 FL	*- FL	
					<b>Sub Total (\$)</b>	<b>29,819.80</b>	<b>4,717.85</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,321.98	402.79
					<b>Total Parts (\$)</b>	<b>28,497.82</b>	<b>4,315.06</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	1,800.00	600.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,600.00	700.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO REMOVE & REFIX REAR REVERSE SENSOR	New	150.00	30.00
5	TO REMOVE & REFIX REAR CAMERA	New	150.00	0.00
6	TO APPLY ANTI RUST ON AFFECTED PARTS	New	120.00	40.00
7	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
8	TO REMOVE & REFIX REAR EXHAUST PIPE	New	150.00	0.00
9	TO REMOVE & REFIX REAR FLOOR ALUMINIUM PLATE	New	300.00	0.00
10	TO REMOVE & REFIX REAR TAILGATE ALUMINIUM PLATE	New	200.00	0.00
11	TO REMOVE & REFIX BOTH REAR SIDE GATE ALUMINIUM PLATE	New	400.00	0.00
12	TO REMOVE & REFIX REAR CANOPY TO FACILITATE REPAIRS	New	450.00	0.00
13	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,000.00</b>	<b>1,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >