



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC23004291/Any3e2

Date: 22/06/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 4789U	Veh. Inspected	GBJ 4861D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1216491-002	Excess (\$)	0.00
Assign From	JESS TOH	Assign Date	26/04/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTFHT02P200248925	Colour	SILVER
Odometer	105899 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	TOURADOR	6 mm
L/H Front Tyre	195 R15C	TOURADOR	6 mm
R/H Rear Tyre	195 R15C	LONG WAY	6 mm
L/H Rear Tyre	195 R15C	LONG WAY	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/03/2023	Inspect Date / Time	26/04/2023 (03:48 PM)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**