

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23004303/CVP3M4**Date:** 06/06/2023**REFERENCE**

Insured/Claimant:	KEE KOH LEONG	Policy No:	SP2003708419	Claim No:	202332007572
Date of Loss:	16/04/2023	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFU8889T		Engine No:	8ARZ148496
Make & Model:	TOYOTA HARRIER, 2.0 M GRADE (A)		Chassis No:	JTEZB3GH30J004158
Reg. Date:	07/01/2019 (Man. Year: 2018)		Odometer:	71116 km
Colour:	White			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	S\$120,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,922.50	3,696.00	1,226.50	24.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,320.00	1,010.00	43.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,252.50	5,016.00	2,236.50	30.84
+ GST 8.00/8.00% (S\$)	580.20	401.28	178.92	30.84
Nett Amount (S\$)	7,832.70	5,417.28	2,415.42	30.84

INSPECTION

Date of Assignment:	26/04/2023	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	26/04/2023	Inspected At:	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722
Estimated Period of Repair:	5.0 days		

Adjuster: SIMON HO LEONG CHUAN**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFU8889T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH (WCP)	Buckled	380.00 F	*380.00 F
2	1		*FRONT FENDER COWLING RH (WCP)	Distorted	185.00 F	*185.00 F
3	10		*FRONT FENDER COWLING CLIPS (WCP)	Necessary	25.00 F	*20.00 F
4	1		*FRONT SPORT RIM RH (WCP)	Cut	1,680.00 F	*1,680.00 F
5	1		*FRONT WHEEL HUB RH BEARING (WCP)	Not Necessary	250.00 F	*- F
6	1		*FRONT KNUCKLE ARM RH (WCP)	Not Necessary	240.00 F	*- F
7	1		*FRONT LOWER ARM RH (WCP)	Not Necessary	220.00 F	*- F
8	1		*FRONT DOOR RH (WCP)	Buckled	720.00 F	*720.00 F
9	1		*FRONT DOOR STICKER RH (WCP)	Necessary	90.00 F	*90.00 F
10	1		*FRONT DOOR CHROME MOULDING RH (WCP)	Cut	125.00 F	*125.00 F
11	1		*FRONT DOOR PILLAR RH (REPAIR) (NPA)	Repair	-	-
12	1		*REAR DOOR RH (REPAIR) (NPA)	Repair	-	-
13	1		*REAR DOOR CHROME MOULDING RH (WCP)	Cut	90.00 F	*90.00 F
14	1		*ROCKER PANEL GARNISH RH (WCP)	Not Necessary	400.00 F	*- F

Supplementary #1

15	2		*FRONT DOOR INNER STICKER RH (WCP)	Necessary	70.00 F	*70.00 F
----	---	--	---------------------------------------	-----------	---------	----------

F=Franchise part.

Sub Total (\$)	4,475.00	3,360.00
+ Margin on L,N Items 10.00/10.00% (\$)	447.50	336.00
Total Parts (\$)	4,922.50	3,696.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK & STRAIGTEN FRONT DOOR PILLAR RH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	600.00	400.00
2	SPRAY PAINT FRONT FENDER RH, FRONT DOOR PILLAR RH, FRONT DOOR RH, REAR DOOR RH. (PEARL COLOUR)	New	1,400.00	800.00
3	REMOVE & REPLACE FRONT DOOR INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM	New	60.00	60.00
4	REMOVE & REPLACE FRONT DOOR PILLAR GARNISH RH, COVERING TRIM	New	60.00	0.00
5	REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION RH	New	150.00	0.00
6	COMPUTER WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (S\$)			2,330.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >