



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 6584Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER RH (SN)	DISTORTED	1,200.00	800.00
1	TAILLAMP (SN)	CRACKED	300.00	300.00
1	TAILLAMP PANEL (SN)	DISTORTED	250.00	250.00
1	REAR BOX PILLAR (SN)	TO REPAIR SEE LABOUR	1,200.00	-
1	REAR BOX PILLAR COVER PLATE (SN)	BENT	600.00	500.00
1	HYDRAULIC FLUID (SN)	NECESSARY	150.00	100.00
1	HYDRAULIC FLUID CONTAINER (SN)	DEFORMED	250.00	250.00
1	HYDRAULIC FLUID CONTAINER COVER (SN)	CRACKED	500.00	400.00
			4,450.00	2,600.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR BOX PILLAR.		1,000.00	600.00
	SPRAY PAINTING TO AFFECTED AREA.		600.00	350.00
	WIRING CHECK.		50.00	30.00
	TO APPLY TUFF COAT.		150.00	40.00
			1,800.00	1,020.00
<b>GRAND TOTAL</b>			<b>6,250.00</b>	<b>3,620.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,900.00</b>

Report Ref No. CS/SMO23004307/Acy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.