

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988**Our File No:** CS/EGI23004325/KVY3E2**Date:** 27/06/2023**REFERENCE**

Insured/Claimant:	KEE MENG SUAN	Policy No:	DMPG23001918	
Date of Loss:	25/04/2023	Nature of Claim:	OD	Claim No: CDMPG23001002

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SND8430C</b>	Engine No:	G4FMMU107786
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHLN41ETNU258956
Reg. Date:	27/01/2022 (Man. Year: 2021)	Odometer:	43504 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$124,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,446.20	3,181.10	265.10	7.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	2,420.00	900.00	27.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,766.20</b>	<b>5,601.10</b>	<b>1,165.10</b>	<b>17.22</b>
<b>- Excess (S\$)</b>	0.00	500.00	-500.00	
<b>(S\$)</b>	6,766.20	5,101.10	1,665.10	24.61
<b>+ GST 7.00/8.00% (S\$)</b>	473.64	408.09	65.55	13.84
<b>Nett Amount (S\$)</b>	<b>7,239.84</b>	<b>5,509.19</b>	<b>1,730.65</b>	<b>23.90</b>

**INSPECTION**

Date of Assignment:	26/04/2023	Present Location:	Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected:	27/04/2023	Inspected At:	Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	6.0 days		

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2023)
<b>Parts:</b>	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SND8430C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BUMPER</b> (WCP)	Bent	285.00 F	*285.00 F
2	1		<b>*FRONT BUMPER CLIPS</b>	Necessary	60.00 FS	*60.00 FS
3	1		<b>*FRONT BUMPER LOGO</b> (WCP)	Necessary	35.00 F	*35.00 F
4	1		<b>*FRONT RADIATOR GRILLE</b> (WCP)	Cut	185.00 F	*185.00 F
5	1		<b>*FRONT BUMPER LOWER GRILLE</b> (WCP)	Cut	115.00 F	*115.00 F
6	1		<b>*FRONT BUMPER AIRDUCT</b> (WCP)	Cut	25.00 F	*20.00 F
7	1		<b>*FRONT BUMPER TOP</b> (WCP)	Repair	95.00 F	*- F
8	1		<b>*FRONT BUMPER SIDE RETAINER RH</b> (WCP)	Distorted	28.00 F	*28.00 F
9	1		<b>*RH HEADLAMP</b> (WCP)	Cracked	750.00 F	*750.00 F
10	1		<b>*RH FRONT FENDER</b> (WCP)	Bent	410.00 F	*410.00 F
11	1		<b>*RH FRONT FENDER UNDERSHIELD</b> (WCP)	Distorted	65.00 F	*65.00 F
12	1		<b>*RH FRONT FENDER UNDERSHIELD CLIPS</b>	Necessary	40.00 FS	*40.00 FS
13	1		<b>*RH FRONT DOOR</b> (WCP)	Bent	850.00 F	*850.00 F
14	1		<b>*RH FRONT DOOR TOP HINGE</b> (WCP)	Repair	38.00 F	*- F
15	1		<b>*RH FRONT DOOR LOWER HINGE</b> (WCP)	Repair	38.00 F	*- F
16	1		<b>*RH FRONT DOOR GARNISH</b> (WCP)	Necessary	30.00 F	*30.00 F
17	1		<b>*RH FRONT DOOR INNER SEAL</b> (WCP)	Serviceable	65.00 F	*- F
<b>Supplementary #1</b>						
18	1		<b>*RH HEADLAMP SUPPORT</b> (WCP)	Cracked	28.00 F	*28.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$)</b>	<b>3,142.00</b>	<b>2,901.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	304.20	280.10
<b>Total Parts (\$)</b>	<b>3,446.20</b>	<b>3,181.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO FOCUS HEADLAMP/ CHECK LIGHT SYSTEM	New	50.00	20.00
2	COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00
3	TO TRANSFER FRONT DOOR PARTS	New	100.00	60.00
4	TO REPAIR/ RESPRAY RH FRONT SPORTS RIM	New	200.00	80.00
5	TO REPAIR BONNET , RH ROCKER PANEL, RH REAR DOOR , RH REAR FENDER, REAR BUMPER INCLUDES REPLACEMENT OF PARTS	New	850.00	600.00
6	TO SPRAY PAINTING BONNET, FRONT BUMPER,FRONT BUMPER TOP, RH FRONT FENDER, RH FRONT DOOR,RH REAR DOOR, RH ROCKER PANEL,REAR BUMPER	New	2,000.00	1,600.00
<b>Gross Labour Cost (\$)</b>			<b>3,320.00</b>	<b>2,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >