

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS6/AIS23004336/CNP3E2  
**Date:** 14/06/2023**REFERENCE**

Insured/Claimant:	FOOD FRESH PTE LTD	Policy No:	SP2005614707-01	
Date of Loss:	24/04/2023	Nature of Claim:	OD	Claim No: 202332007651

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YR1G</b>		
Make & Model:	HINO XZU710R, 4.0 D 14FT WID CAB 5T MT (M)	Engine No:	N04CWN21012
Reg. Date:	30/03/2023 (Man. Year: 2022)	Chassis No:	JHHUCV3F70K048022
Colour:	White	Odometer:	0 km
Engine Capacity:	4009 cc		
Market Value/New Car Price:	S\$123,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	0 mm	Rear Left Side:	0 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,575.90	4,596.90	979.00	17.56
Miscellaneous Items	85.00	85.00	0.00	0.00
Labour	1,770.00	1,420.00	350.00	19.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,430.90</b>	<b>6,101.90</b>	<b>1,329.00</b>	<b>17.88</b>
<b>- Excess (S\$)</b>	700.00	700.00	0.00	0.00
<b>(S\$)</b>	6,730.90	5,401.90	1,329.00	19.74
<b>+ GST 8.00/8.00% (S\$)</b>	538.47	432.15	106.32	19.74
<b>Nett Amount (S\$)</b>	<b>7,269.37</b>	<b>5,834.05</b>	<b>1,435.32</b>	<b>19.74</b>

**INSPECTION**

Date of Assignment:	27/04/2023		
Date Inspected:	26/04/2023	Inspected At:	Blk 8, Sin Ming Ind. EstateE #01-60/62 Sector C Singapore 575643. Repairer: City Auto Pte Ltd (HQ)
Estimated Period of Repair:	6.0 days		

**Adjuster:** SIMON HO LEONG CHUAN**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Jun 2023)	
<b>Parts:</b>	N/A	HINO XZU710R 4.0 D 14FT WID CAB 5T MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YR1G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Front bumper</b> (WCP)	Buckled	250.00 F	*450.00 F
2	1		<b>*Front bumper bracket LH</b> (WCP)	Bent	185.00 F	*185.00 F
3	1		<b>*Front bumper bracket RH</b> (WCP)	Bent	185.00 F	*185.00 F
4	1		<b>*Front bumper reinforcement</b> (WCP)	Dented	95.00 F	*95.00 F
5	2		<b>*Foglamp</b> (WCP)	Not Necessary	440.00 F	*- F
6	2		<b>*Headlamp</b> (WCP)	Cracked	1,100.00 F	*1,100.00 F
7	1		<b>*Front grille logo</b> (WCP)	Missing	80.00 F	*80.00 F
8	8		<b>*Front grille clip</b> (WCP)	Necessary	16.00 F	*16.00 F
9	1		<b>*RH corner panel</b> (WCP)	Missing	155.00 F	*155.00 F
10	4		<b>*RH corner panel clip</b> (WCP)	Necessary	8.00 F	*8.00 F
11	1		<b>*Front outer panel</b> (WCP)	Buckled	320.00 F	*320.00 F
12	1		<b>*Front inner panel</b> (WCP)	Repair	650.00 F	*- F
13	1		<b>*Sticker - Hino</b> (WCP)	Necessary	95.00 F	*95.00 F
14	1		<b>*Sticker - 300</b> (WCP)	Necessary	85.00 F	*85.00 F
15	1		<b>*Front step garnish RH</b> (WCP)	Cracked	245.00 F	*245.00 F
16	1		<b>*Front grille base</b> (WCP)	Missing	285.00 F	*285.00 F
17	1		<b>*Front windscreen glass moulding</b> (WCP)	Necessary	195.00 F	*195.00 F
18	1		<b>*Front grille</b> (WCP)	Missing	680.00 F	*680.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>5,069.00</b>	<b>4,179.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	506.90	417.90
<b>Total Parts (\$\$)</b>	<b>5,575.90</b>	<b>4,596.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>Glass sealant</b> (NECESSARY)	40.00	40.00
2	1	<b>License plate</b> (MISSING)	20.00	20.00
3	1	<b>License plate casing</b> (CRACKED)	25.00	25.00
<b>Sub Total (S\$)</b>			<b>85.00</b>	<b>85.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	- To remove and install front windscreen glass	New	120.00	120.00
2	To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	850.00	700.00
3	Spray painting on affected and replace parts	New	800.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>1,770.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >