



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 3848C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT BUMPER | BUCKLED | 498.20 | 498.20 |
| 1 | FRONT BUMPER SIDE RETAINER LH | DISTORTED | 21.50 | 21.50 |
| 1 | FRONT HEADLAMP LH | MTG CRACKED | 763.60 | 763.60 |
| 1 | FRONT HEADLAMP BRACKET LH | SERVICEABLE | 24.00 | - |
| 1 | FRONT FENDER LH | BENT | 566.70 | 547.20 |
| 1 | FRONT FENDER INNER SHIELD LH | DISTORTED | 87.80 | 87.80 |
| 1 | FRONT LH DOOR | TO REPAIR SEE LABOUR | 1,993.00 | - |
| 1 | REAR LH DOOR | TO REPAIR SEE LABOUR | 1,643.00 | - |
| | LESS 20% DISCOUNT | | -1,119.56 | -383.66 |
| | | | 4,478.24 | 1,534.64 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET FRONT BUMPER CLIPS (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | SET FRONT FENDER INNER SHIELD CLIPS (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | RIM (SN) | DENTED | 900.00 | 450.00 |
| 1 | TYRE (225/45R17) (SN) | SERVICEABLE | 300.00 | - |
| | | | 1,300.00 | 550.00 |
| | <u>LABOUR</u> | | | |
| | SPRAY PAINT ON ALL AFFECTED AREA . | | 1,200.00 | 800.00 |
| | LABOUR REMOVE /REFIX ACCIDENT DAMAGE PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF FRONT LH DOOR AND REAR LH DOOR . | | 1,000.00 | 500.00 |
| | TO CHECK WIRING SYSTEM. | | 100.00 | 20.00 |
| | TO APPLY ANTI RUST TREATMENT. | | 120.00 | 30.00 |
| | TO CHECK & ADJUST WHEEL ALIGNMENT. | | 100.00 | 60.00 |
| | TO REMOVE /REFIX /REPLACE FRONT & REAR LH WINDOW GLASS ,MECHANSIAM & ETC TO NEW DOOR . | NOT NECESSARY | 300.00 | - |
| | TO REMOVE /REFIX/REPLACE TYRE & RIM . | | 100.00 | 20.00 |
| | | | 2,920.00 | 1,430.00 |
| | GRAND TOTAL | | 8,698.24 | 3,514.64 |

Report Ref No. CS/AGI23004342/Kvy3q2



| | | | |
|---|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 2,800.00 |
|---|--|--|-----------------|

Report Ref No. CS/AGI23004342/Kvy3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.