

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23004346/RNP3Q2**Date:** 25/07/2023**REFERENCE**

|                              |                                               |                             |                          |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMHCSNA00012762200       |
| <b>Claimant Vehicle No :</b> | SGD7172L                                      | <b>Insured Vehicle No :</b> | SNB4339X                 |
| Date of Loss:                | 24/04/2023                                    | Nature of Claim:            | TP                       |
|                              |                                               | Claim No:                   | SNM23D203013/C02/KHONGLH |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SGD7172L</b>                   | Engine No:  | FB20YE25071       |
| Make & Model:               | SUBARU FORESTER, 2.0 (A)          | Chassis No: | JF1SJ5KC5JG111372 |
| Reg. Date:                  | 09/07/2018 (Man. Year: 2018)      | Odometer:   | 143358 km         |
| Colour:                     | Black                             |             |                   |
| Engine Capacity:            | 1995 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/60 R17   | Rear Tyre Size:  | 225/60 R17   |
| Front Left Side:  | Hankook 6 mm | Rear Left Side:  | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 11,514.95         | 9,250.00          | 2,264.95          | 19.67         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 14,125.00         | 8,305.00          | 5,820.00          | 41.20         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>25,639.95</b>  | <b>17,555.00</b>  | <b>8,084.95</b>   | <b>31.53</b>  |
| <b>+ GST 8.00/8.00% (S\$)</b> | <b>2,051.20</b>   | <b>1,404.40</b>   | <b>646.80</b>     | <b>31.53</b>  |
| <b>Nett Amount (S\$)</b>      | <b>27,691.15</b>  | <b>18,959.40</b>  | <b>8,731.75</b>   | <b>31.53</b>  |

**INSPECTION**

|                             |            |                                                                                                  |
|-----------------------------|------------|--------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 27/04/2023 |                                                                                                  |
| Date Inspected:             | 02/05/2023 | Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee)<br>25 Leng Kee Road<br>Singapore 159097 |
| Estimated Period of Repair: | 9.0 days   |                                                                                                  |

**Adjuster:** MOHD RASUL**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                           |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                           |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 25 Jul 2023)             |
| Parts:        | M1-SUV                                                                                                                                                                       | SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                         |
| Print Code:   | (Unsubmitted, no print-code for SGD7172L)                                                                                                                                    |                                                           |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                           |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                           |

Recommended Parts

| No.                          | Qty | Part No. | Particulars                                    | Condition     | Repairer's        | Amount             |
|------------------------------|-----|----------|------------------------------------------------|---------------|-------------------|--------------------|
| 1                            | 1   |          | *SUNDRIES                                      | Necessary     | 100.00 FS         | *20.00 FS          |
| 2                            | 1   |          | *EXH PIPE ASSY R                               | Bent          | 765.90 FS         | *765.90 FS         |
| 3                            | 1   |          | *MUFFLER ASSY RH NA                            | Bent          | 617.90 FS         | *617.90 FS         |
| 4                            | 1   |          | *FLOOR PAN R R CP                              | Repair        | 444.00 FS         | *- FS              |
| 5                            | 1   |          | *SKIRT COMPL REAR END PANEL                    | Bent          | 296.00 FS         | *296.00 FS         |
| 6                            | 1   |          | *BUMPER FACE REAR FORESTER IL                  | Cracked       | 610.50 FS         | *610.50 FS         |
| 7                            | 1   |          | *BRKT CORNER F RH                              | Not Necessary | 37.00 FS          | *- FS              |
| 8                            | 1   |          | *BRKT CORNER F LH                              | Not Necessary | 37.00 FS          | *- FS              |
| 9                            | 1   |          | *BRKT SD F RH                                  | Not Necessary | 13.00 FS          | *- FS              |
| 10                           | 1   |          | *BRKT SD F LH                                  | Not Necessary | 13.00 FS          | *- FS              |
| 11                           | 1   |          | *BRKT SD R RH                                  | Necessary     | 14.80 FS          | *14.80 FS          |
| 12                           | 1   |          | *BRKT SD R LH                                  | Necessary     | 14.80 FS          | *14.80 FS          |
| 13                           | 1   |          | *BUMPER FRT (FOR HL/W)                         | Deformed      | 610.50 FS         | *610.50 FS         |
| 14                           | 1   |          | *BACK BEAM CPL F                               | Not Necessary | 296.00 FS         | *- FS              |
| 15                           | 1   |          | *BEAM COMPL R EU                               | Bent          | 296.00 FS         | *296.00 FS         |
| 16                           | 1   |          | *ENERGY ABSOR F                                | Bent          | 129.50 FS         | *129.50 FS         |
| 17                           | 1   |          | *COVER HOOK R                                  | Not Necessary | 13.00 FS          | *- FS              |
| 18                           | 1   |          | *COVER BMPR R (EXHAUST)                        | Not Necessary | 14.80 FS          | *- FS              |
| 19                           | 1   |          | *COVER HOOK F SP                               | Not Necessary | 5.55 FS           | *- FS              |
| 20                           | 1   |          | *PANEL CPL R/G NA                              | Bent          | 1,102.60 FS       | *1,102.60 FS       |
| 21                           | 1   |          | *GLASS R/G                                     | Necessary     | 821.40 FS         | *821.40 FS         |
| 22                           | 1   |          | *RUBBER DAM GLS                                | Necessary     | 7.40 FS           | *7.40 FS           |
| 23                           | 1   |          | *RUBBER R/G                                    | Necessary     | 13.00 FS          | *13.00 FS          |
| 24                           | 1   |          | *WSTR DR R G                                   | Not Necessary | 111.60 FS         | *- FS              |
| 25                           | 9   |          | *CLIP BMPR                                     | Necessary     | 21.60 FS          | *21.60 FS          |
| 26                           | 2   |          | *CLIP                                          | Necessary     | 6.00 FS           | *6.00 FS           |
| 27                           | 1   |          | *LETTER MK R IMPS/SPORT                        | Necessary     | 72.00 FS          | *72.00 FS          |
| 28                           | 1   |          | *LETTER MARK FORESTOR R                        | Necessary     | 40.70 FS          | *40.70 FS          |
| 29                           | 1   |          | *LETTER MK R SUB                               | Necessary     | 66.60 FS          | *66.60 FS          |
| 30                           | 1   |          | *CARGO STEP PANEL S/S                          | Deformed      | 460.00 FS         | *460.00 FS         |
| 31                           | 1   |          | *FRONT GRILLE                                  | Not Necessary | 1,200.00 FS       | *- FS              |
| 32                           | 1   |          | *FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS) | Cracked       | 1,398.00 FS       | *1,398.00 FS       |
| 33                           | 1   |          | *FORESTER 2.0I-S KIT REAR UNDER SPOILER (TCS)  | Cracked       | 1,702.00 FS       | *1,702.00 FS       |
| 34                           | 1   |          | *FRONT NUMBER PLATE                            | Bent          | 45.00 FS          | *45.00 FS          |
| 35                           | 1   |          | *GASKET                                        | Necessary     | 7.40 FS           | *7.40 FS           |
| 36                           | 2   |          | *R EXH CUTTER RH/LH                            | Bent          | 74.00 FS          | *74.00 FS          |
| 37                           | 1   |          | *REFLEC AY RH                                  | Cracked       | 20.40 FS          | *20.40 FS          |
| 38                           | 1   |          | *BOLT SP TIRE HLDRM8                           | Necessary     | 10.40 FS          | *10.40 FS          |
| 39                           | 1   |          | *SUPPORTER HOLDER                              | Necessary     | 5.60 FS           | *5.60 FS           |
| F=Franchise part. S=SpcNett. |     |          |                                                |               |                   |                    |
|                              |     |          |                                                |               | Total Parts (S\$) | 11,514.95 9,250.00 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                              | Lab.Type | Repairer's       | Amount          |
|--------------------------------|--------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>            |                                                                          |          |                  |                 |
| 1                              | REPLACE FRONT BUMPER ENERGY ABSORBER ,BUMPER BEAM AND FRT GRILLE         | New      | 3,500.00         | 600.00          |
| 2                              | REPLACE REAR BUMPER ,BUMPER BEAM ,END PANEL ,SPARE TYRE FLOOR & TAILGATE | New      | 3,500.00         | 3,000.00        |
| 3                              | RESPRAY FRONT BUMPER & BUMPER BEAM                                       | New      | 1,600.00         | 600.00          |
| 4                              | RESPRAY REAR BUMPER ,BUMPER BEAM,END PANEL ,SPARE TYRE FLOOR & TAILGATE  | New      | 3,500.00         | 2,500.00        |
| 5                              | TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)                              | New      | 100.00           | 80.00           |
| 6                              | TRANSFER TAILGATE MECHANISM                                              | New      | 150.00           | 150.00          |
| 7                              | INSTALL REAR WINDSCREEN                                                  | New      | 300.00           | 300.00          |
| 8                              | TO SUPPLY & INSTALL REAR WINDSCREEN SOLAR FILM                           | New      | 145.00           | 145.00          |
| 9                              | TO CONDUCT WATER SEEPAGE TEST                                            | New      | 100.00           | 30.00           |
| 10                             | REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR             | New      | 150.00           | 80.00           |
| 11                             | TO SUPPLY & INSTALL FRONT SENSOR -2EYES                                  | New      | 300.00           | 80.00           |
| 12                             | TO INSTALL REAR CARGO STEP PANEL                                         | New      | 100.00           | 60.00           |
| 13                             | INSTALL FRONT & REAR UNDER SPOILER                                       | New      | 250.00           | 250.00          |
| 14                             | FAULT DIAGNOSTIC (RESET)                                                 | New      | 280.00           | 280.00          |
| 15                             | REMOVE & REFIX EXHAUST SYSTEM                                            | New      | 150.00           | 150.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                          |          | <b>14,125.00</b> | <b>8,305.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >