



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 9444B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DAMAGED	879.00	581.00
1	FRT BUMPER SIDE RETAINER LH	NOT NECESSARY	45.00	-
1	FRT BUMPER BRACKET LH	NOT NECESSARY	52.00	-
1	FRT BUMPER REINFORCEMENT SPONGE	NOT NECESSARY	189.00	-
1	FRT BUMPER GRILLE	NOT NECESSARY	212.00	-
1	FRT BUMPER FOGLAMP COVER LH	SCRATCHED	124.00	85.65
1	FRT BUMPER FOGLAMP LH	NOT NECESSARY	358.00	-
1	FRT HEADLAMP LH	SCRATCHED	2,159.00	1,588.72
1	FRT HEADLAMP LOWER BRACKET LH	NOT NECESSARY	75.00	-
1	FRT GRILLE	NOT NECESSARY	512.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	698.00	-
1	FRONT FENDER COWLING LH	NOT NECESSARY	159.00	-
1	FRONT FENDER EMBLEM HYBRID	NECESSARY	62.00	62.00
1	FRT LOWER ARM LH	NOT NECESSARY	581.00	-
1	FRT KNUCKLE ARM LH	NOT NECESSARY	587.00	-
1	FRT WHEEL BEARING LH	NOT NECESSARY	198.00	-
	LESS 25% DISCOUNT		-1,722.50	-579.34
			5,167.50	1,738.03
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRT BUMPER CLIP (SN)	NECESSARY	50.00	20.00
1	SET FRT FENDER INNERSHIELD CLIP LH (SN)	NOT NECESSARY	50.00	-
1	FRONT RIM LH (SN)	SCRATCHED	800.00	400.00
			900.00	420.00
	<u>LABOUR</u>			
	CHECK WIRING.		100.00	30.00
	R+R FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	RESET TROUBLE CODE.	NOT NECESSARY	400.00	-
	REALIGN HEADLAMP.	NOT NECESSARY	120.00	-

Report Ref No. CS/LIP23004347/Wwy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	KNOCK. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH. SPRAY.		800.00	400.00
			800.00	400.00
			2,670.00	830.00
GRAND TOTAL			8,737.50	2,988.03
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS/LIP23004347/Wwy3e2

MARKET VALUE: \$162,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$72,987.00=NETT VALUE: \$89,013.00

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.