

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	F	Ref:	CS/INC23004351/Aqy3m4	
	75 BRAS BASAH R INCOME CENTRES	Γ	Date:	23/06/2023	
	ATTN: NATALIE LE	E	C	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 4833C	Veh. Inspected		GBL 256S
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1219436-002	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		27/04/2023
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c		2754
	Engine No.	HIDDEN	Year of Reg.		2021
	Chassis No.	GDH2011053086	Colour		WHITE
	Odometer	74051 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15C	DUNLOP		6 mm
	L/H Front Tyre	195 R15C	DUNLOP		6 mm
	R/H Rear Tyre	195 R15C	DUNLOP		6 mm
	L/H Rear Tyre	195 R15C	DUNLOP		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
	D/ W// CEO CEE DE	TITULO.			
5. General Information					
	Accident Date	19/04/2023	Inspect Date / Ti	ime	27/04/2023 ( 04:38 PM )
	Survey held at HD PERFECT AUTOWORK PTE LTD				
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
5b.	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.  Estimate Days of Repair				
55.	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				