

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004352/KVP3Q2**Date:** 06/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00001802300
Claimant Vehicle No :	VGW779	Insured Vehicle No :	SGP1806T
Date of Loss:	12/04/2023	Nature of Claim:	TP
		Claim No:	SNM23D202744/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	VGW779	Engine No:	2ARJ141321
Make & Model:	TOYOTA VELLFIRE, 2.5 CVT (A)	Chassis No:	AGH300213750
Reg. Date:	01/01/2018 (Man. Year: 2018)	Odometer:	51842 km
Colour:	Metallic Dark Purple		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50Z R18	Rear Tyre Size:	235/50Z R18
Front Left Side:	Farroad 8 mm	Rear Left Side:	Farroad 8 mm
Front Right Side:	Farroad 8 mm	Rear Right Side:	Farroad 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,947.92	7,978.51	10,969.41	57.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,720.00	2,510.00	2,210.00	46.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,667.92	10,488.51	13,179.41	55.68
Approved Total (Overridden) (S\$)		8,400.00		
Nett Amount (S\$)	23,667.92	8,400.00	15,267.92	64.51

INSPECTION

Date of Assignment:	27/04/2023	
Date Inspected:	03/05/2023	Inspected At: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2023)
Parts: M1-MPV	TOYOTA VELLFIRE 2.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for VGW779)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,126.95 FL	*- FL
2	1		*SET TAILGATE GLASS MOULDING	Not Necessary	241.55 FL	*- FL
3	1		*TAILGATE LAMP -RH	Cut	891.62 FL	*721.80 FL
4	1		*TAILGATE W/STRIP	Serviceable	366.93 FL	*- FL
5	2		*TAILGATE SEAMING SEALS-L/R	Serviceable	883.00 FL	*- FL
6	1		*TAILLAMP -RH	Cut	1,266.43 FL	*845.00 FL
7	1		*TAILLAMP FILLER PANEL -RH	Repair	481.95 FL	*- FL
8	1		*REAR BUMPER	Bent	1,658.63 FL	*1,217.00 FL
9	1		*REAR BUMPER TOW COVER -RH	Serviceable	81.50 FL	*- FL
10	1		*REAR BUMPER REFLECTOR -RH	Broken	131.45 FL	*131.45 FL
11	1		*REAR BUMPER SPLASH SHIELD -RH	Cracked	181.92 FL	*181.92 FL
12	1		*REAR BUMPER SIDE RETAINERS -L/R	O/S Distorted	224.70 FL	*112.35 FL
13	1		*REAR END PANEL	Repair	861.90 FL	*- FL
14	1		*REAR END PANEL TRIM	Serviceable	261.95 FL	*- FL
15	1		*REAR FENDER -RH	Bent	1,655.92 FL	*1,655.92 FL
16	1		*SET REAR FENDER GLASS MOULDING	Necessary	281.93 FL	*281.93 FL
17	1		*REAR FENDER AIR VENT	Dented	114.75 FL	*114.75 FL
18	1		*REAR FENDER INNER SHIELD	Serviceable	216.35 FL	*- FL
19	1		*REAR FENDER INNER TRIM BOARD -RH	Buckled	1,366.51 FL	*986.00 FL
20	1		*REAR FENDER INNER PANEL	Repair	1,055.90 FL	*- FL
21	1		*REAR EXHAUST SILENCER	Repair	931.65 FL	*- FL
22	3		*REAR EXHAUST MOUNTINGS	Serviceable	84.30 FL	*- FL
23	1		*REAR SHOCK ABSORBER -RH	Serviceable	441.65 FL	*- FL
24	1		*REAR WHEEL HUB WITH BEARING -RH	Bent	761.90 FL	*432.00 FL
25	1		*A/C BLOWER ASSY -REAR	Housing Cracked	1,899.50 FL	*1,450.00 FL
26	1		*TAILLAMP LOWER GARNISH -RH	Buckled	631.80 FL	*307.90 FL
27	1		*TAILLAMP LOWER GARNISH RETAINER	Serviceable	141.25 FL	*- FL
28	1		*SET TAILGATE GLASS SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*SET TAILGATE GLASS FOAM TAPE	Not Necessary	65.00 FS	*- FS
30	1		*SET TAILLAMP LOWER GARNISH CLIP	Necessary	80.00 FS	*50.00 FS
31	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
32	1		*SET REAR FENDER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*SET REAR BUMPER LOWER SPOILER	Dented / Cut	1,800.00 FS	*900.00 FS
34	1		*SET REAR REVERSE SENSOR	Serviceable	450.00 FS	*- FS
35	1		*SET REAR BUMPER LOWER CHROME MOULDING	Necessary	800.00 FS	*200.00 FS
36	1		*REAR SPORT WHEEL -RH	Dented	650.00 FS	*400.00 FS
37	1		*REAR TYRE -RH	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,758.89	10,088.02
- List Item Discount on L Items 25.00/25.00% (\$)	4,810.97	2,109.51
Total Parts (\$)	18,947.92	7,978.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE ,REFIX TAILGATE /FENDER GLASS	New	300.00	80.00
3	TO REMOVE ,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	100.00
4	TO REMOVE ,REFIX REAR EXHAUST	New	120.00	60.00
5	TO REMOVE ,REFIX REAR UNDERCARRIAGE	New	250.00	60.00
6	TO REMOVE, REFIX A/C COOLING SYSTEM & REFILL A/C GAS	New	180.00	100.00
7	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
8	TO RESPRAY UNDERCOATING	New	150.00	30.00
9	TO RESPRAY PAINTING AND ETC	New	1,600.00	900.00
10	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,800.00	1,100.00
Gross Labour Cost (S\$)			4,720.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >