

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|---|-----------------|-------------------------|--|
| | HSBC LIFE (SING) | APORE) PTE LTD | Ref | : CS/HSB23004357/Awp3e2 | |
| | 10 MARINA BOULI #48-01 MARINA BA 2SINGAPORE 018 | AY FINANCIAL CENTRE TOWER | Dat | e: 18/05/2023 | |
| | ATTN: OH VALE | | Cod | de: HSB | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SH 9293U | Veh. Inspected | SKU 5024H | |
| | Policy No. | VFX/P2419138 | Coverage (\$) | 0.00 | |
| | Claim No. | S3M04M0W | Excess (\$) | 0.00 | |
| | Assign From | OH VALE | Assign Date | 27/04/2023 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | VOLKSWAGEN SHARAN | c.c | 1984 | |
| | Engine No. | HIDDEN | Year of Reg. | 2015 | |
| | Chassis No. | WVWZZZ7NZFV034854 | Colour | GREY | |
| | Odometer | 104954 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 225/50 R17 | BRIDGESTONE | 6 mm | |
| | L/H Front Tyre | 225/50 R17 | BRIDGESTONE | 6 mm | |
| | R/H Rear Tyre | 225/50 R17 | BRIDGESTONE | 6 mm | |
| | L/H Rear Tyre | 225/50 R17 | BRIDGESTONE | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 25/04/2023 | Inspection Date | 02/05/2023 | |
| | Survey held at | JEC AUTO SERVICE PTE LTD | | | |
| | | 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | |