

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23004365/RVP3Q2**Date:** 26/06/2023**REFERENCE**

Insured/Claimant: KWEE CHIU LIN, JACQUELINE MRS JACQUELINE SEOW

Policy No: SP2003999756

Date of Loss: 15/03/2023

Nature of Claim: OD Claim No: 202332006295

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SCU8628R**

Make & Model: VOLKSWAGEN GOLF, 1.4 TSI HL RL (A)

Engine No: CZCC11860

Reg. Date: 22/01/2021 (Man. Year: 2020)

Chassis No: WVVZZZAUZLW117027

Colour: Grey

Odometer: 19887 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$126,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,569.03	7,765.24	5,803.79	42.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,860.00	4,240.00	1,620.00	27.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,429.03	12,005.24	7,423.79	38.21
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	18,829.03	11,405.24	7,423.79	39.43
+ GST 8.00/8.00% (S\$)	1,506.32	912.42	593.90	39.43
Nett Amount (S\$)	20,335.35	12,317.66	8,017.69	39.43

INSPECTION

Date of Assignment: 27/04/2023

Date Inspected: 04/05/2023 Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2023)
Parts:	144	VOLKSWAGEN GOLF 1.4 TSI HL RL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCU8628R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD	Bent	1,453.92 FS	*1,453.92 FS
2	1		*LOCKING CATCH	Not Necessary	65.01 FS	*- FS
3	1		*HOOD LATCH	Not Necessary	167.17 FS	*- FS
4	1		*FLAMP HINGE LHF	Not Necessary	77.81 FS	*- FS
5	1		*FLAMP HINGE RHF	Not Necessary	77.81 FS	*- FS
6	1		*GAS-FILLED STRUT	Not Necessary	107.81 FS	*- FS
7	1		*LED HEADLIGHT RHF	Cracked	2,284.88 FS	*2,284.88 FS
8	1		*LED HEADLIGHT LHF	Not Necessary	2,284.88 FS	*- FS
9	2		*CONTROL UNIT FOR LIGHT CO	Not Necessary	641.84 FS	*- FS
10	2		*POWER MODULE FOR MAIN LIG	Not Necessary	744.70 FS	*- FS
11	1		*CROSS SUPPORT RHF	Bent	32.23 FS	*32.23 FS
12	1		*CROSS SUPPORT LHF	Bent	32.23 FS	*32.23 FS
13	1		*RADIATOR GRILLE BLACK/SAT	Cracked	526.03 FS	*526.03 FS
14	1		*VW SIGN BLACK /BRIGHT CHRO	Cracked	76.84 FS	*76.84 FS
15	1		*COVER FOR BUMPER PRIMED FRT BUMPER	Deformed	1,179.22 FS	*1,179.22 FS
16	1		*GUIDE PIECE LHF BUMPER BRACKET (SIDE)	Necessary	26.73 FS	*26.73 FS
17	1		*GUIDE PIECE RHF BUMPER BRACKET (SIDE)	Necessary	26.73 FS	*26.73 FS
18	1		*SUPPORT PART LHF BUMPER BRACKET (OUTER)	Not Necessary	45.37 FS	*- FS
19	1		*SUPPORT PART RHF BUMPER BRACKET (OUTER)	Not Necessary	45.37 FS	*- FS
20	1		*SENSOR BRACKET	Necessary	11.15 FS	*11.15 FS
21	2		*SENSOR BRACKET	Necessary	21.38 FS	*21.38 FS
22	1		*SENSOR BRACKET	Necessary	11.15 FS	*11.15 FS
23	1		*SEAL RING SATIN BLACK (4 PCS)	Necessary	4.41 FS	*4.41 FS
24	4		*SENSOR PRIMED	Not Necessary	560.53 FS	*- FS
25	1		*2K-PLASTIC ADHESIVE	Necessary	60.94 FS	*60.94 FS
26	1		*BONDING AGENT FOR PLASTIC	Necessary	53.55 FS	*53.55 FS
27	1		*FOAM INSERT	Not Necessary	53.06 FS	*- FS
28	1		*IMPACT BEAM REINFORCEMENT	Bent	617.92 FS	*617.92 FS
29	1		*POP-RIVET (4 PCS)	Necessary	2.53 FS	*2.53 FS
30	1		*LICENSE PLATE BRACKET SAT	Bent	75.20 FS	*75.20 FS
31	1		*RIVET (4 PCS)	Necessary	1.38 FS	*1.38 FS
32	1		*COOLING AIR GRILL SATIN B	Not Necessary	147.72 FS	*- FS
33	1		*DECORATIVE MOULDING BLACK CTR	Not Necessary	89.42 FS	*- FS
34	1		*DECORATIVE MOULDING BLACK LHF	Not Necessary	63.37 FS	*- FS
35	1		*DECORATIVE MOULDING BLACK	Not Necessary	63.37 FS	*- FS
36	1		*COOLING AIR GRILL SATIN B LHF	Not Necessary	110.25 FS	*- FS
37	1		*COOLING AIR GRILL SATIN B RHF	Not Necessary	110.25 FS	*- FS
38	1		*DECORATIVE MOULDING BLACK LHF	Not Necessary	90.37 FS	*- FS
39	1		*DECORATIVE MOULDING BLACK RHF	Not Necessary	90.37 FS	*- FS
40	1		*RETAINER FOR SPOILER SATI	Not Necessary	167.31 FS	*- FS
41	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
42	1		*LOCK CARRIER WITH MOUNTIN	Cracked	939.36 FS	*939.36 FS
43	1		*SUPPORT FOR LOCK CARRIER	Necessary	37.59 FS	*37.59 FS
44	1		*BUMPER CTR BRACKET	Cracked	61.50 FS	*61.50 FS

Report was unsubmitted during this print-out.

6/26/23, 3:41 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*RHS AIR GUIDE	Cracked	22.27 FS	*22.27 FS
46	2		*COOLANT 1B	Necessary	36.20 FS	*36.20 FS
47	1		*SEAL RING	Necessary	5.58 FS	*5.58 FS
48	1		*SEAL RING	Necessary	5.93 FS	*5.93 FS
49	1		*(0.1) OIL FOR REFRIGERANT	Necessary	18.39 FS	*18.39 FS
50	1		*A/C GAS	Necessary	60.00 FS	*60.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					13,569.03	7,765.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	2,800.00	2,240.00
2	SPRAY PAINTING	New	2,120.00	1,060.00
3	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	200.00	200.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
5	TO ALIGN LED HEADLIGHT	New	100.00	100.00
6	B&P LEAKED CHECK ,VACUUM & REGAS	New	280.00	280.00
Gross Labour Cost (S\$)			5,860.00	4,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >