

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9960C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR LH OUTER MOULDING	DENTED	125.30	125.30
	LESS 20% DISCOUNT		-25.06	-25.06
			100.24	100.24
	NETT ITEMS			
1	REAR DOOR (ZIG) APPS LH (N)	NECESSARY	80.00	80.00
1	REAR FENDER (PETROL ONLY) LH (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-11.00	-11.00
			99.00	99.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
			1,000.00	850.00
	GRAND TOTAL		1,199.24	1,049.24
	DECOMMENDED COST OF LUMP CUM DEPAIRS			050.00

RECOMMENDED COST OF LUMP SUM REPAIRS		850.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC23004373/Svp3m4

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser