

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23004383/CWP3M4**Date:** 16/06/2023**REFERENCE**

Insured/Claimant: CHOW KONG KEONG Policy No: SP2003183997-01
Date of Loss: 18/04/2023 Nature of Claim: OD Claim No: 202332007437

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS8373S**
Make & Model: BMW 520i, 2.0 (A) Engine No: 26005628B48B20A
Reg. Date: 31/10/2019 (Man. Year: 2019) Chassis No: WBAJA12020WW35462
Colour: Blue Odometer: 52259 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$170,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,466.45	1,924.40	1,542.05	44.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,292.00	2,172.00	1,120.00	34.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,758.45	4,096.40	2,662.05	39.39
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	6,158.45	3,496.40	2,662.05	43.23
+ GST 8.00/8.00% (\$\$)	492.68	279.71	212.97	43.23
Nett Amount (\$\$)	6,651.13	3,776.11	2,875.02	43.23

INSPECTION

Date of Assignment: 28/04/2023
Date Inspected: 02/05/2023 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941
Estimated Period of Repair: 3.0 days

Adjuster: SIMON HO LEONG CHUAN**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jun 2023)
Parts:	143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS8373S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 8JX18 DOUBLE SPK 634	Not Necessary	1,207.35 FS	*- FS
3	1		*HUB CAP WITH CHROME EDGE	Not Necessary	32.25 FS	*- FS
4	1		*(S/L) LH PROTECTION FOIL	Not Necessary	14.15 FS	*- FS
5	1		*(S/L) RH PROTECTION FOIL	Not Necessary	14.15 FS	*- FS
6	1		*REAR BUMPER RH SIDE GUIDE	Distorted	179.90 FS	*179.90 FS
7	1		*REAR BUMPER TRIM STRIP	Not Necessary	119.40 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Cut	1,664.50 FS	*1,664.50 FS
9	1		*SET MOUNTING PMA SENSOR	Not Necessary	73.75 FS	*- FS
10	2		*(S/L) CLIP	Not Necessary	11.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					3,466.45	1,924.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS. (1X)	New	531.00	0.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING. (1X). RIGHT REAR	New	94.00	0.00
Gross Labour Cost (S\$)			3,292.00	2,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >