

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 4082L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEAD LAMP	CUT	262.00	262.00
1	HEAD LAMP BRACKET	NOT NECESSARY	85.00	-
1	HEAD LAMP COWLING ASSY	CRACKED	220.00	220.00
1	HANDLE BAR	NOT NECESSARY	168.00	-
1	SET HANDLE GRIP L/R	BENT	60.00	60.00
1	HANDLE BRAKE LEVER	BENT	62.00	62.00
1	HANDLE CLUTCH LEVER	NOT NECESSARY	62.00	-
1	FRONT FORK ASSY	NOT NECESSARY	280.00	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	115.00	-
2	FRONT SIGNAL LAMP L/R	NOT NECESSARY	220.00	-
1	SET BODY COVERSET COWLING	CRACKED	860.00	500.00
2	SET FRONT FOOTREST L/R	BENT	142.00	142.00
1	FOOT GEAR SELECTOR LEVER	BENT	74.00	74.00
1	FOOT BRAKE LEVER	BENT	145.00	145.00
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	168.00	-
1	EXHAUST HEAT SHIELD	BENT	385.00	80.00
	LESS 5% DISCOUNT		-165.40	-
	LESS 10% DISCOUNT		-	-154.50
			3,142.60	1,390.50
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	20.00	-
			20.00	-
	<u>LABOUR</u>			
	CHECK WIRING SYSTEM AND LIGHT.		80.00	30.00
	FORK ALIGNMENT.		80.00	60.00
	WHEEL ALIGNMENT.		100.00	50.00
	SPRAY PAINTING.		700.00	300.00

Report Ref No. CS3/ASM21013327/Dnp3e2-1



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR FOR REPAIR AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER AND EXHAUST PIPE.		1,000.00	300.00
			1,960.00	740.00
	GRAND TOTAL		5,122.60	2,130.50

RECOMMENDED COST OF LUMP SUM REPAIRS		1,700.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS3/ASM21013327/Dnp3e2-1



**Automotive Assessor / Investigator**