

TO : LONPAC INSURANCE BHD

FAX NO:

ESTIMATE REPORT 1ST Quotation

03/05/2023 14:56

OWNER'S PARTICULARS

JOB-NO: 85008979

NAME: LIMELITE PRODUCTIONS PTE
ADDRESS: NA

CONTACT: NA
NA
NA@HOTMAIL.COM

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: GBM2624U TRANS: AUTO
MAKE / MODEL: BYD / T3
OWNER'S INSURER: LONPAC INSURANCE BHD
JOB-CODE: OD SA: Ding Auto User 1

CHASSIS: LC0CE4DB5N0403731
ENGINE: TZ180XSC122090177

CLAIM DETAILS

| DESCRIPTION | QTY | QUOTED COSTS | DISCOUNT | DISC PRICE | IND | SUR.DISP | REV PRICE |
|--|------|--------------|----------|------------|-----|----------|-----------|
| LABOUR | | | | | | | |
| 1 STRAIGHT AND PANEL BEAT ACCIDENT AREA | 1.00 | 1,000.00 | 0.00 | 1,000.00 | Y | | 660 |
| 2 SUNDRIES | 1.00 | 50.00 | 0.00 | 50.00 | Y | | 20 |
| 3 RUST PROOFING | 1.00 | 80.00 | 0.00 | 80.00 | Y | | 40 |
| 4 DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM | 1.00 | 180.00 | 0.00 | 180.00 | Y | | 100 |
| 5 ADJUST HEADLAMP AIM | 1.00 | 60.00 | 0.00 | 60.00 | Y | | 30 |
| 6 R&R RADIATOR & A/C CONDENSER & ELECTRONIC FAN | 1.00 | 180.00 | 0.00 | 180.00 | Y | | 120? |
| 7 VACUUM & TOP UP AIR COND GAS R-134A | 1.00 | 150.00 | 0.00 | 150.00 | Y | | 100? |
| 8 SPRAY PAINT FOR FRONT BUMPER | 1.00 | 250.00 | 0.00 | 250.00 | Y | | 250 |
| 9 SPRAY PAINT FOR FRONT FENDER LH | 1.00 | 250.00 | 0.00 | 250.00 | Y | | X |
| 10 SPRAY PAINT FOR FRONT FENDER RH | 1.00 | 250.00 | 0.00 | 250.00 | Y | | X |
| 11 SPRAY PAINT FOR ENGINE HOOD & HINGE | 1.00 | 350.00 | 0.00 | 350.00 | Y | | 220 |
| 12 SPRAY PAINT FOR LEFT FENDER | 1.00 | 250.00 | 0.00 | 250.00 | Y | | 250 |
| 13 SPRAY PAINT FOR RIGHT FENDER | 1.00 | 250.00 | 0.00 | 250.00 | Y | | 250 |
| 14 SPRAY PAINT FOR RADIATOR CROSSBEAM & PILLAR | 1.00 | 250.00 | 0.00 | 250.00 | Y | | 200 |
| TOTAL: | | 3,550.00 | 0.00 | 3,550.00 | | | |

MATERIALS

| | | | | | | | |
|---|------|----------|------|----------|---|---|-------|
| 1 RUBBER BUSHING, BRACKET ? | 2.00 | 1.70 | 0.00 | 1.70 | L | Y | _____ |
| 2 RADIATOR ASSY ? | 1.00 | 557.05 | 0.00 | 557.05 | L | Y | _____ |
| 3 ELECTRONIC FAN ? | 1.00 | 523.34 | 0.00 | 523.34 | L | Y | _____ |
| 4 RUBBER CUSHION, LOWER SUSPENSION ? | 2.00 | 10.84 | 0.00 | 10.84 | L | Y | _____ |
| 5 A/C CONDENSER ASSY ? | 1.00 | 709.02 | 0.00 | 709.02 | L | Y | _____ |
| 6 COMBINATION LAMP ASSY, FL <i>crn</i> | 1.00 | 844.09 | 0.00 | 844.09 | L | Y | _____ |
| 7 COMBINATION LAMP ASSY, FR <i>crn</i> | 1.00 | 844.09 | 0.00 | 844.09 | L | Y | _____ |
| 8 CHARGING PORT LIGHT ASSY ? | 1.00 | 18.40 | 0.00 | 18.40 | L | Y | _____ |
| 9 CONDENSER PIPE ASSY 1 ? | 1.00 | 337.66 | 0.00 | 337.66 | L | Y | _____ |
| 10 OUTER PIPE ASSY, COMPRESSOR ? | 1.00 | 128.26 | 0.00 | 128.26 | L | Y | _____ |
| 11 BRACKET, FRONT BUMPER R <i>Me</i> | 1.00 | 17.76 | 0.00 | 17.76 | L | Y | _____ |
| 12 GRILLER, RADIATOR <i>san de</i> | 1.00 | 756.24 | 0.00 | 756.24 | L | Y | _____ |
| 13 LEFT COVER, REAR GRILLE - GREY 6 <i>san</i> | 1.00 | 77.63 | 0.00 | 77.63 | L | Y | _____ |
| 14 LEFT COVER, FRONT GRILLE - GREY 6 <i>san</i> | 1.00 | 77.63 | 0.00 | 77.63 | L | Y | _____ |
| 15 BRACKET, FRONT BUMPER, L <i>Me</i> | 1.00 | 17.76 | 0.00 | 17.76 | L | Y | _____ |
| 16 FRONT BUMPER <i>de</i> | 1.00 | 1,105.70 | 0.00 | 1,105.70 | L | Y | _____ |
| 17 PLUG, THE FRONT TOW HOOK <i>san</i> | 1.00 | 7.44 | 0.00 | 7.44 | L | Y | _____ |

CLAIM DETAILS

| DESCRIPTION | QTY | QUOTED COSTS | DISCOUNT | DISC PRICE | IND | SUR.DISP | REV PRICE |
|---|------|------------------|-------------|------------------|-----|----------|-----------|
| 18 INTAKE GRID, FRONT BUMPER <i>(m)</i> | 1.00 | 126.55 | 0.00 | 126.55 | L | Y | _____ |
| 19 BRACE ASSY, FRONT FOGLIGHT, L <i>?</i> | 1.00 | 177.28 | 0.00 | 177.28 | L | Y | _____ |
| 20 BRACE ASSY, FRONT FOGLIGHT, R <i>?</i> | 1.00 | 160.37 | 0.00 | 160.37 | L | Y | _____ |
| 21 ENGINE HOOD ASSY <i>bt</i> | 1.00 | 3,393.04 | 0.00 | 3,393.04 | L | Y | _____ |
| 22 LEFT FENDER <i>repair</i> | 1.00 | 1,679.67 | 0.00 | 1,679.67 | L | Y | _____ |
| 23 RIGHT FENDER <i>repair</i> | 1.00 | 1,679.67 | 0.00 | 1,679.67 | L | Y | _____ |
| 24 BRACKET I, CHARGING PORT <i>?</i> | 1.00 | 219.40 | 0.00 | 219.40 | L | Y | _____ |
| 25 FRAME ASSY, FRONT BUMPER <i>?</i> | 1.00 | 1,257.57 | 0.00 | 1,257.57 | L | Y | _____ |
| 26 RADIATOR LEFT PILLAR <i>?</i> | 1.00 | 1,232.26 | 0.00 | 1,232.26 | L | Y | _____ |
| 27 RADIATOR LOWER BEAM <i>?</i> | 1.00 | 1,004.35 | 0.00 | 1,004.35 | L | Y | _____ |
| 28 RADIATOR RIGHT PILLAR <i>?</i> | 1.00 | 1,232.26 | 0.00 | 1,232.26 | L | Y | _____ |
| 29 RIGHT CONNECTING PLATE, RADIATOR UPPER BEAM <i>?</i> | 1.00 | 354.46 | 0.00 | 354.46 | L | Y | _____ |
| 30 LEFT CONNECTING PLATE, RADIATOR UPPER BEAM <i>?</i> | 1.00 | 354.46 | 0.00 | 354.46 | L | Y | _____ |
| 31 UPPER CROSSBEAM ASSY, RADIATOR <i>bt/pldo?</i> | 1.00 | 2,194.50 | 0.00 | 2,194.50 | L | Y | _____ |
| 32 HINGE ASSY, ENGINE HOOD, L <i>bt</i> | 1.00 | 33.71 | 0.00 | 33.71 | L | Y | _____ |
| 33 HINGE ASSY, ENGINE HOOD, R <i>bt</i> | 1.00 | 33.71 | 0.00 | 33.71 | L | Y | _____ |
| 34 LOCK ASSY, FRONT CABIN LID <i>?</i> | 1.00 | 121.56 | 0.00 | 121.56 | L | Y | _____ |
| 35 FRONT BUMPER CLIP SET <i>na</i> | 1.00 | 45.00 | 0.00 | 45.00 | L | Y | 30 |
| 36 FRONT NUMBER PLATE & FRAME <i>ms</i> | 1.00 | 65.00 | 0.00 | 65.00 | S | Y | 50 |
| 37 RADIATOR COOLANT <i>fill</i> | 1.00 | 50.00 | 0.00 | 50.00 | S | Y | 30 |
| TOTAL: | | 21,449.43 | 0.00 | 21,449.43 | | | _____ |
| TOTAL PARTS & LABOUR : | | 24,999.43 | 0.00 | 24,999.43 | | | _____ |

EXCESS/LOADING:S\$ 0.00

No. Of Day: 6 days

EXCESS:TBA/REPAIR

RE-SURVEY: ~~BEFORE~~ AFTER PAINTING
 PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: 03 / 05 23 @ 1615

SURVEYED BY: Rahul

CONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001
 Ding Auto User 1

ESTIMATOR
 STA AUTOCENTRE
 TEL: _____ FAX: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____