



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI23004395/Uny3e2	
			Date: 18/05/2023	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SG 6097U	Veh. Inspected	GBF 4805M
	Policy No.		Coverage (\$)	0.00
	Claim No.	D23001480MFBP	Excess (\$)	0.00
	Assign From	JOANNE TAN	Assign Date	28/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE (A)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTFHT02PX00207961	Colour	MULTI COLOUR
	Odometer	121466 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	WEST LAKE	6 mm
	L/H Front Tyre	195 R15	WEST LAKE	6 mm
	R/H Rear Tyre	195 R15	WEST LAKE	6 mm
	L/H Rear Tyre	195 R15	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/04/2023	Inspection Date	03/05/2023
	Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	