



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23004397/Uny3e2 Date: 06/06/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SG 1195C	Veh. Inspected	SKJ 3813T
Policy No.		Coverage (\$)	0.00
Claim No.	D23001474MFBP	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	28/04/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2120362A963913	Colour	BLACK
Odometer	135356 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40Z R18	MICHELIN	6 mm
L/H Front Tyre	245/40Z R18	MICHELIN	6 mm
R/H Rear Tyre	265/35Z R18	MICHELIN	6 mm
L/H Rear Tyre	265/35Z R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/04/2023	Inspection Date	22/05/2023
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	