

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23004398/UWY3M4**Date:** 11/05/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002727970
<b>Claimant Vehicle No :</b>	SLZ633U	<b>Insured Vehicle No :</b>	FBT7812Z
Date of Loss:	27/04/2023	Nature of Claim:	TP
		Claim No:	312709

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ633U	Engine No:	2ZR8270874
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S CVT (A)	Chassis No:	ZVW506102998
Reg. Date:	23/04/2018 (Man. Year: 2017)	Odometer:	177741 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	KAPSEN 5 mm	Rear Left Side:	RAPID 5 mm
Front Right Side:	KAPSEN 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,769.87	3,404.40	4,365.47	56.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,110.00	1,150.00	50.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,029.87</b>	<b>4,514.40</b>	<b>5,515.47</b>	<b>54.99</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,029.87</b>	<b>3,600.00</b>	<b>6,429.87</b>	<b>64.11</b>

INSPECTION

Date of Assignment:	04/05/2023		
Date Inspected:	02/05/2023	Inspected At:	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-05/53, BARTLEY BIZ CENTRE, SINGAPORE 417808
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ633U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed/Torn	1,450.00 FL	*781.20 FL
2	1		*FRONT BUMPER SIDE RETAINER	N/S Cracked/ O/S Not Necessary	196.00 FL	*98.00 FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	312.00 FL	*- FL
4	1		*FRONT BUMPER LOWER SKIRT	Not Necessary	780.00 FL	*- FL
5	1		*FRONT BUMPER LOWER COVER	Not Necessary	378.00 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP LHS	Not Necessary	592.50 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP INNER BRACKET LHS	Not Necessary	142.00 FL	*- FL
8	2		*FRONT BUMPER TOW COVER	Not Necessary	144.00 FL	*- FL
9	1		*FRONT BUMPER CENTRE BADGE	Not Necessary	98.00 FL	*- FL
10	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	372.00 FL	*- FL
11	1		*LHS HEADLAMP	Scratched/Cracked	1,280.00 FL	*1,280.00 FL
12	1		*LHS FRONT FENDER	Dented/Bent	982.00 FL	*982.00 FL
13	1		*LHS FRONT FENDER HYBRID EMBLEM	Necessary	126.00 FL	*90.00 FL
14	1		*LHS FRONT FENDER INNER SPLASH SHIELD	Torn	245.00 FL	*245.00 FL
15	1		*LHS FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
16	1		*LHS FRONT DOOR GLASS	Serviceable	650.00 FL	*- FL
17	1		*LHS SIDE VIEW MIRROR ASSY	Broken	410.00 FL	*410.00 FL
18	1		*LHS SIDE VIEW MIRROR COVER	Broken	178.00 FL	*178.00 FL
19	1		*LHS SIDE VIEW MIRROR	Broken	395.00 FL	*395.00 FL
20	1		*FRONT LICENCE PLATE W/HOLDER (NPA)	Not Necessary	0.00 FS	*- FS
21	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*SET FRONT FENDER INNER SHIELD CLIPS LHS	Necessary	60.00 FS	*30.00 FS
23	1		*FRONT FENDER/ BUMPER SECURING CLIP LHS	Not Necessary	42.00 FS	*- FS
24	1		*LHS FRONT SPORTS RIM (CUT)	Not Consistent With The Impact	980.00 FS	*- FS
25	1		*FRONT BUMPER LOWER COVER CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,952.50	4,519.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,182.63	1,114.80
Total Parts (\$\$)	7,769.87	3,404.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS; REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	380.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED (FRONT DOOR)	New	900.00	680.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS AND FOCUS HEADLAMP BEAM	New	150.00	20.00
4	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	0.00
5	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	90.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,260.00</b>	<b>1,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >