



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 21006-02/MY / 2021
Date of Report : 15 Sep 2021

Nicholas Ng
Blk 19 Anchorvale Crescent
#16-19
Singapore 544653

*Submit 4/5 @ 6300
4 days*

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 8 Feb 2021

*Replaced Exhaust
to report page 54-55*

Workshop Address : 1 Genesis Pte Ltd
421 Tagore Industrial Ave
#03-31
Singapore 787805

As per your instruction dated **11 Feb 2021**
carried out a physical inspection on the said vehicle
our report and findings as follows:

with regard to the above matter. We have
SME 7807 M. We enclosed herewith

1. VEHICLE PARTICULARS

Registration No : SME 7807 M
Model : Audi TT RS
Year / Capacity : 2011/2480
Chassis No : TRUZZZ8J7A1901480

Engine No : CEP002954
Mileage : 112808
Colour : White

2. TYRES CONDITION

	Size	Made	Balance	Rim
FRONT O/S	225/45 R18	Good Year	4.00 mm	Sport
REAR O/S	255/40 R18	Good Year	4.00 mm	Sport
FRONT N/S	225/45 R18	Good Year	4.00 mm	Sport
REAR N/S	255/40 R18	Good Year	4.00 mm	Sport

Vehicle No: **SME 7807 M**
 Report No: **TP/ 21006-02/MY / 2021**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Boot lid	Repair	\$ 2700.93	\$ 11 X
1	Boot lid rubber	Intact	\$ 180.00	\$ Su X
2	Rear taillamps	Damage	\$ 835.40	\$ CM 835.40 ✓
1	Rear end panel	Damage	\$ 700.97	\$ R 700.97 X
1	Rear end panel inner garnish	Intact	\$ 270.99	\$ Su X
1	Rear bumper	Damage	\$ 2030.77	\$ Dis 2030.77 ✓
2	Rear bumper side brackets	Damage	\$ 84.00	\$ Sel 84.00 ✓
1	Rear bumper inner sponge	Damage	\$ 182.00	\$ Toa 182.00 ✓
1	Rear bumper lower grille	Damage	\$ 369.50	\$ Dis 369.50 ✓
1	Rear bumper centre lamp	Damage	\$ 230.00	\$ Bro 230.00 ✓
2	Rear bumper side retainers	Damage	\$ 101.54	\$ Daye 101.54 ✓
4	Rear bumper PDC sensors	Damage	\$ 1156.00	\$ Daye 1156.00 2pc 578 ✓
2	Rear bumper side guides	Damage	\$ 116.00	\$ CR 116.00 ✓
1	Rear tow hook cover	Damage	\$ 40.97	\$ mis 40.97 ✓
1	Rear exhaust silencer	Damage	\$ 2467.30	\$ Sel 2467.30 ✓
2	Rear exhaust silencer mountings	Necessary	\$ 199.54	\$ All 199.54 ✓
1	Rear exhaust silencer insulator	Damage	\$ 299.70	\$ R 299.70 X
			\$ 11965.61	\$ 8813.69
	Discount	5.0%	\$ 598.28	\$ 440.68
			\$ 11367.33	\$ 8373.01

photo 52?

Spare Parts Total \$ 11367.33 \$ 8373.01

Vehicle No: **SME 7807 M**
 Report No: **TP/ 21006-02/MY / 2021**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 11367.33	\$ 8373.01
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 80.00	\$ 40.00 <i>20</i>
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 160.00	\$ 80.00 ✓
3	To remove and refit rear bumper sensor.	\$ 200.00	\$ 120.00 <i>50</i>
4	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 200.00	\$ 120.00 <i>100</i>
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1100.00	\$ 750.00 <i>400</i>
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1000.00	\$ 750.00 <i>400</i>
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ <i>11</i> 60.00 <i>X</i>
Total		<u>\$ 14257.33</u>	<u>\$ 10293.01</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 8200.00

SDLS: EIGHT THOUSAND TWO HUNDRED ONLY


 Qualified Appraiser

8-7235.02
52
6873.26
1050
7923.26
6528



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 6 working days to complete.
5. Enclosed number of photograph : 145 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.