

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580

Our File No: CS/III23004411/KNY3M4**Date:** 18/07/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT A CAR PTE LTD Policy No: D20MFL0000326_02

Date of Loss: 16/04/2023

Nature of Claim: OD

Claim No: MFL2023D0004527

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB2062G**
 Make & Model: MAZDA 6, 2.0 SEDAN EXECUTIVE I5 (A) Engine No: PE21601571
 Reg. Date: 05/08/2021 (Man. Year: 2021) Chassis No: JM6GL1073M0454781
 Colour: Metallic Blue Odometer: 29913 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: S\$118,000.00
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
 Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,844.00	5,540.80	303.20	5.19
Miscellaneous Items	71.00	71.00	0.00	0.00
Labour	1,280.00	820.00	460.00	35.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,195.00	6,431.80	763.20	10.61
- Excess (\$\$)	0.00	750.00	-750.00	
(\$\$)	7,195.00	5,681.80	1,513.20	21.03
+ GST 8.00/8.00% (\$\$)	575.60	454.54	121.06	21.03
Nett Amount (\$\$)	7,770.60	6,136.34	1,634.26	21.03

INSPECTION

Date of Assignment: 02/05/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
 Date Inspected: 02/05/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
 205 Braddell Road
 Singapore 579701
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2023)
Parts:	143	MAZDA 6 2.0 SEDAN EXECUTIVE I5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB2062G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,212.00 FL	*1,212.00 FL
2	5		*FRONT BUMPER RIVET TYPE A	Necessary	40.00 FL	*40.00 FL
3	5		*FRONT BUMPER RIVET B	Necessary	20.00 FL	*20.00 FL
4	1		*FRONT RADIATOR LH CHROME	Cracked	304.00 FL	*304.00 FL
5	1		*FRONT LOWER GRILLE LH CHROME	Dented	80.00 FL	*80.00 FL
6	1		*FRONT BUMPER LH RETAINER	Distorted	15.00 FL	*15.00 FL
7	1		*LH HEADLAMP	Mtg Cracked	5,137.00 FL	*4,758.00 FL
8	1		*FRONT LH FENDER	Buckled	373.00 FL	*373.00 FL
9	1		*FRONT LH FENDER INNER LINER	Cracked	124.00 FL	*124.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	7,305.00 6,926.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,461.00 1,385.20
					Total Parts (S\$)	5,844.00 5,540.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS Necessary	30.00	30.00
2	1	FRONT LH FENDER INNER LINER CLIPS Necessary	30.00	30.00
3	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			71.00	71.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	600.00	400.00
2	To putty & respray on Front damage area.	New	600.00	400.00
3	To check wiring & focus headlamp.	New	80.00	20.00
Gross Labour Cost (\$\$)			1,280.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >