



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 5746Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAILGATE	BENT	1,282.50	1,282.50
1	HONDA LOGO EMBLEM	NECESSARY	38.70	38.70
1	REAR BUMPER	BUCKLED	987.50	681.30
1	SET REAR WINDSCREEN MOULDINGS	NECESSARY	252.80	200.16
	LESS 20% DISCOUNT		-512.30	-440.53
			2,049.20	1,762.13
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SEALANT (SN)	NECESSARY	40.00	40.00
			40.00	40.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE + REFIX REAR WINDSCREEN.		160.00	120.00
	TO CHECK / CLEAR FAULT CODES AFTER REPAIR.	NOT NECESSARY	80.00	-
	TO TRANSFER PARKING SENSORS & REVERSING CAMERA.		80.00	50.00
	TO DISMANTLE + RENEW PARTS.		450.00	400.00
	TO SPRAY PAINT (PEARL PAINT).		600.00	500.00
			1,370.00	1,070.00
<b>GRAND TOTAL</b>			<b>3,459.20</b>	<b>2,872.13</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,872.13</b>

Report Ref No. CS/AGI23004415/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.