

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 03 May 2023

Preliminary Advice

Vehicle No	: PA88C	Accident Date	: 22/04/2023
Make	: TOYOTA HIACE	Policy No.	:
			DMB1SNA00017532201
Assignment Date	: 02/05/2023	Excess	: S\$2,000.00
Date of Inspection	: 2/5/2023	Est. Duration of Repair	: 10
Inspection At	: CENTURY MOTORS PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,388.13
Revised Amount	:S\$	4,440.13
Check Items (Estimated)	:S\$	6,978.00
Total	:S\$	11,418.13
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	135,000.00
COE / PARF Rebate	:S\$	47,350.00
Salvage Value	:S\$	
Margin for Repair	:S\$	87,650.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by part repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .

At the time of inspection, brake in order and tyre condition in good serviceable condition with remaining tread depth of approximately 6 mm