

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23004422/UQP3E2**Date:** 17/07/2023REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00024202200

**Claimant Vehicle  
No :** FBP9906U**Insured Vehicle  
No :** SMP1219S

Date of Loss: 25/04/2023

Nature of Claim: TP

Claim  
No: SNM23D203035/C02/TAYHPDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBP9906U**

Make &amp; Model: YAMAHA AEROX 155A, 155cc

Engine No: G3J8E0104429

Reg. Date: 11/07/2019 (Man. Year: 2019)

Chassis No: MH3SG4640KJ055735

Colour: White

Odometer: 63578 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRES

Front Tyre Size: 110-80-14

Rear Tyre Size: 140-70-14

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,724.00	1,216.80	507.20	29.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,113.00	375.00	738.00	66.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,837.00</b>	<b>1,591.80</b>	<b>1,245.20</b>	<b>43.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,250.00</b>		
<b>(S\$)</b>	2,837.00	1,250.00	1,587.00	55.94
<b>+ GST 8.00/8.00% (S\$)</b>	226.96	100.00	126.96	55.94
<b>Nett Amount (S\$)</b>	<b>3,063.96</b>	<b>1,350.00</b>	<b>1,713.96</b>	<b>55.94</b>

INSPECTION

Date of Assignment: 02/05/2023

Date Inspected: 02/05/2023 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)  
BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial  
City  
Singapore 533758

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 17 Jul 2023)	
<b>Parts:</b>	N/A	YAMAHA AEROX 155A 155cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBP9906U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE WHEEL	Bent	13.00 F	*13.00 FL
2	1		*BOARD FOOTREST	Distorted	32.00 F	*32.00 FL
3	1		*BOARD FOOTREST 2	Not Necessary	32.00 F	*- FL
4	1		*BRACKET HEADLIGHT	Bent	39.00 F	*39.00 FL
5	1		*COVER FRONT (BLACK)	Cut	16.00 F	*16.00 FL
6	1		*COVER FRONT 2	Cut	5.00 F	*5.00 FL
7	1		*COVER INNER FENDER	Distorted	34.00 F	*34.00 FL
8	1		*COVER INNER SIDE COVER	Distorted	19.00 F	*19.00 FL
9	1		*FOOTREST SIDE COVER RH	Not Necessary	34.00 F	*- FL
10	1		*FORK FRONT ASSY	Bent / Twisted	656.00 F	*656.00 FL
11	1		*HEADLAMP ASSY	Cut	427.00 F	*427.00 FL
12	1		*PLATE PROBATION (3M)	Necessary	36.00 FS	*36.00 FS
13	1		*PROTECTOR MUFFLER (CARBON)	Not Necessary	310.00 F	*- FL
14	1		*SET STEERING CONE	Necessary	71.00 F	*71.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,724.00</b>	<b>1,348.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	131.20
<b>Total Parts (\$\$)</b>	<b>1,724.00</b>	<b>1,216.80</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	ALIGNMENT BODY	New	350.00	0.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	688.00	300.00
3	SPRAY PAINT COVER FRONT UPPER	New	30.00	30.00
4	SPRAY PAINT MUDGUARD FRONT	New	45.00	45.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,113.00</b>	<b>375.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >