

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23004431/KWP3Q2
Date: 23/05/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	Z22VC05011822
Claimant Vehicle No :	GBF1004C	Insured Vehicle No :	SNB5019M
Date of Loss:	26/04/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF1004C	Engine No:	ZD30012417N
Make & Model:	NISSAN CABSTAR, 2.0 (M)	Chassis No:	JN1SC2F24Z0858771
Reg. Date:	23/06/2016 (Man. Year: 2016)	Odometer:	376661 km
Colour:	Gold		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 2/2 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,996.50	5,842.20	2,154.30	26.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	1,460.00	10.00	0.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,466.50	7,302.20	2,164.30	22.86
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	9,466.50	5,500.00	3,966.50	41.90

INSPECTION

Date of Assignment:	02/05/2023	
Date Inspected:	03/05/2023 Inspected At:	Rc Auto-160 Sin Ming (HQ) 160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 23 May 2023)	
Parts:	N/A	NISSAN CABSTAR 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF1004C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,575.60 F	*1,399.00 FN
2	1		*REAR EMBLEM STICKER	Necessary	186.60 F	*186.60 FN
3	1		*REAR LAMP	Cracked	188.90 F	*188.90 FN
4	1		*REAR TAILGATE HINGE LOCK	Bent	259.00 F	*259.00 FN
5	1		*REAR TAILGATE RUBBER STOPPER	Missing	25.00 F	*25.00 FN
6	1		*REAR CENTRE PIPE (TO CAT)	Bent	1,560.00 F	*1,560.00 FN
7	1		*REAR END PIPE	Bent	280.00 FS	*280.00 FS
8	1		*REAR LEAF SPRING	O/S Bent / Distorted	2,777.00 F	*1,388.50 FN
9	1		*REAR EXHAUST HOOK	Torn	122.80 FS	*122.80 FS
10	1		*REAR TYRE FASTENER CHAIN	Missing	250.00 FS	*250.00 FS
11	1		*REAR NO PLATE LAMP	Missing	105.00 F	*105.00 FN
12	1		*AIRBAG ECU	Shorted	156.60 FS	*156.60 FS
13	1		*REAR CENTRE CROSS MEMBER	Bent	230.00 F	*230.00 FN
14	1		*NUMBER PLATE	Bent	30.00 FS	*25.00 FS
15	1		*SET REVERSE SENSOR	Dented	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	7,996.50	6,376.40
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	534.20
Total Parts (\$\$)	7,996.50	5,842.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	120.00	120.00
2	TO REPLACE REAR EXHAUST AND CENTRE EXHAUST	New	70.00	70.00
3	TO CHECK WIRING	New	30.00	20.00
4	TO REMOVE REAR FLOORBOARD TO FACILITATE REPAIR	New	150.00	150.00
5	TO RESPRAY ABOVE PARTS	New	400.00	400.00
6	TO STRAIGHTEN REAR CHASIS AND TO RENEW	New	700.00	700.00
			Gross Labour Cost (S\$)	1,470.00
				1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >