

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23004452/UVY3Q2**Date:** 11/05/2023REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SNF540K**Insured Vehicle No :** SMZ6588R

Date of Loss: 27/04/2023

Nature of Claim: TP

Claim No: DMPC2300312H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNF540K**

Make & Model: BMW 116I, 1.5 (A)

Engine No: 27195631074212

Reg. Date: 09/09/2009 (Man. Year: 2009)

Chassis No: WDB2110412B338649

Colour: Brown

Odometer: 124935 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size: 245/40Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,241.50	6,681.11	6,560.39	49.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	1,250.00	2,730.00	68.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,221.50	7,931.11	9,290.39	53.95
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	17,221.50	6,300.00	10,921.50	63.42

INSPECTION

Date of Assignment: 02/05/2023

Date Inspected: 03/05/2023 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)

25 Kaki Bukit Road 4, #01-49 Synergy@KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2023)
Parts:	144	BMW 116I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF540K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	2,883.00 FN	*- FN
2	1		*FRONT HEADLAMP -RH	Cracked	3,651.00 FN	*3,066.22 FN
3	1		*FRONT HEADLAMP PANEL	Repair	285.00 FN	*- FN
4	1		*FRONT GRILLE ASSY	Not Necessary	1,150.00 FN	*- FN
5	1		*FRONT BUMPER	Distorted	1,875.00 FN	*1,631.11 FN
6	1		*FRONT BUMPER FOG LAMP (O/S)	Cracked	325.00 FN	*325.00 FN
7	1		*FRONT BUMPER FOG LAMP COVER (O/S)	Twisted	185.00 FN	*185.00 FN
8	1		*FRONT BUMPER INNER SPONGE	Not Necessary	165.00 FN	*- FN
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	195.00 FN	*- FN
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	596.00 FN	*- FN
11	1		*FRONT BUMPER REINFORCEMENT STAY	Not Necessary	155.00 FN	*- FN
12	1		*FRONT BUMPER RUBBER SEAL	Necessary	115.00 FN	*115.00 FN
13	1		*FRONT BUMPER SIDE RETAINER (O/S)	Cracked	75.00 FN	*75.00 FN
14	1		*FRONT BUMPER CHROME MOULDING (O/S)	Distorted	225.00 FN	*182.01 FN
15	1		*FRONT BUMPER SIDE PDC SENSOR	Malfunction	355.00 FN	*198.00 FN
16	1		*FRONT BUMPER SIDE UNDERCOVER	Deformed / Torn	355.00 FN	*355.00 FN
17	1		*FRONT FENDER (O/S)	Bent	995.00 FN	*995.00 FN
18	1		*FRONT FENDER INNER SHIELD (O/S)	Torn	185.00 FN	*185.00 FN
19	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
20	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	13,930.00	7,412.34
- Nett Item Discount on N Items 5.00/10.00% (S\$)	688.50	731.23
Total Parts (S\$)	13,241.50	6,681.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT SENSOR	New	150.00	50.00
3	TO APPLY UNDERCOATING	New	150.00	30.00
4	PANEL BEATING	New	1,600.00	550.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	600.00
6	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	500.00	0.00
Gross Labour Cost (S\$)			3,980.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >