



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RODERIC YUEN

Ref: CS/INC23004455/Rny3e2

Date: 01/06/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMA 419S	Veh. Inspected	SMU 4902G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1220476-002	Excess (\$)	0.00
Assign From	HAZALYSA	Assign Date	03/05/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE 1.6 GLS (A) S	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	KMHD841CMLU098405	Colour	GREY
Odometer	15095 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	6 mm
L/H Rear Tyre	205/55 R16	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/04/2023	Inspect Date / Time	03/05/2023 (03:22 PM)
Survey held at	R&S ENGINEERING WORKS PTE LTD 13, PIONEER SECTOR 1, SINGAPORE 628424		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**