



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS3/FCI22001816/Tqp3e2-1 Date: 15/06/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SMB 5063X	Veh. Inspected	YP 5047C
Policy No.		Coverage (\$)	0.00
Claim No.	D22000550MFBP	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	03/05/2023
2. Vehicle Particulars & Condition			
Make & Model	ISUZU FVR34SUQDC	c.c	7790
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JALFVR347G7001257	Colour	YELLOW
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/80 R22.5	FALKEN	8 mm
L/H Front Tyre	275/80 R22.5	FALKEN	8 mm
R/H Rear Tyre	275/80 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/80 R22.5 (D)	BRIDGESTONE	8/8 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	21/02/2022	Inspection Date	31/05/2023
Survey held at	160, SIN MING DRIVE, #01-03, SIN MING AUTOCITY		
Repairer	TAN HUP SENG AUTO REPAIR WORKSHOP		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR (TMA):		10 Working Days	
ESTIMATED NORMAL PERIOD FOR REPAIR (LORRY):		16 Working Days	