



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 829R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	C&C BADGE (SN)	NECESSARY	50.00	50.00
1	SET REVERSE SENSOR (SN)	MALFUNCTION	220.00	220.00
1	REAR NUMBER PLATE WITH CASING (SN)	SCRATCHED	50.00	50.00
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	COVER-RR BUMPER (SN)	DEFORMED	749.00	749.00
1	COVER-RR BUMPER LWR (SN)	NOT NECESSARY	241.00	-
1	COVER-RR BUMPER UNDER, LH (SN)	NOT NECESSARY	33.00	-
10	CLIP (SN)	NECESSARY	10.00	10.00
1	COVER-RR BUMPER FOG LAMP, LH (SN)	GRAZED	19.00	19.00
1	LAMP ASSY-SIDE T/SIGNAL, LH (SN)	NOT NECESSARY	201.00	-
1	EXTN WIRING ASSY-BWS (SN)	NOT NECESSARY	207.00	-
1	BEAM-RR BUMPER (SN)	SERVICEABLE	318.00	-
1	BRACKET-RR BEAM UPR MTG, LH (SN)	NOT NECESSARY	9.00	-
1	BRACKET-RR BEAM UPR MTG, RH (SN)	NOT NECESSARY	9.00	-
1	BRACKET-RR BEAM LWR, CTR (SN)	NOT NECESSARY	6.00	-
2	BRACKET-RR BEAM LWR MTG (SN)	NOT NECESSARY	12.00	-
1	STAY-RR BUMPER LH (SN)	NOT NECESSARY	65.00	-
1	STAY-RR BUMPER RH (SN)	NOT NECESSARY	65.00	-
1	BRACKET ASSY-RR BPR SIDE UPR, LH (SN)	NOT NECESSARY	25.00	-
1	BRACKET-ASSY RR BPR SIDE UPR, RH (SN)	NOT NECESSARY	31.00	-
1	ANTENNA ASSY-SMARTKEY (SN)	NOT NECESSARY	46.00	-
1	PANEL ASSY-BACK (SN)	TO REPAIR SEE LABOUR	324.00	-
1	BODY KIT (SN)	CRACKED	1,721.00	1,721.00
1	W/STRIP-TRUNK LID OPNG (SN)	NOT NECESSARY	100.00	-
1	TRIM ASSY-RR TRANSVERSE (SN)	NOT NECESSARY	41.00	-
1	PANEL ASSY-TRUNK LID (SN)	DENTED	1,566.00	1,566.00
1	HINGE ASSY-TRUNK LID, LH (SN)	NOT NECESSARY	107.00	-
1	HINGE ASSY-TRUNK LID, RH (SN)	NOT NECESSARY	97.00	-
1	LOGO ASSY-KIA SUB (SN)	NECESSARY	32.00	32.00
1	EMBLEM-CERATO (SN)	NECESSARY	28.00	28.00

Report Ref No. CS/FCI23004485/Uvp3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LAMP ASSY-CENTER GARNISH (SN)	CRACKED	690.00	690.00
1	LAMP ASSY-REAR COMB INSIDE, LH (SN)	CRACKED	608.00	608.00
1	LAMP ASSY-REAR COMB OUTSIDE, LH (SN)	NOT NECESSARY	675.00	-
			8,405.00	5,773.00
	LABOUR			
	TO APPLY SEALANT KIT ON NEW PANEL.		240.00	80.00
	TO APPLY ANTI-CORROSION ON REAR ACCIDENT AFFECTED AREAS.		200.00	100.00
	TO CHECK AND TEST REVERSE SENSOR.		100.00	100.00
	TO REPLACE REAR BODY KIT.	NOT NECESSARY	640.00	-
	TO REMOVE AND REINSTALL TRIMMING AND CARPETING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS.		640.00	320.00
	TO REPLACE TRUNK LID PANEL, REAR BUMPER, REINFORCEMENT, ETC		3,840.00	2,240.00
	-TO CUT & REWELD REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF PANEL ASSY-BACK.			
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		2,750.00	2,200.00
	TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE.		280.00	280.00
	CHECK WIRING & ELECTRICAL SYSTEM.		100.00	80.00
			8,790.00	5,400.00
GRAND TOTAL			17,195.00	11,173.00
RECOMMENDED COST OF REPAIRS				11,173.00

Report Ref No. CS/FCI23004485/Uvp3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.