

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	rog. no. 10000110010 GGT rog. no. 10 0001100 ft					
	Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	AL INSURANCE LTD		Ref:	CS/FCI23004485/Uvp3e2	
	16 RAFFLES QUA #42-01 HONG LEC SINGAPORE 0485	ONG BUILDING		Date:	06/06/2023	
				Code:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBK 1244A	Veh. Inspected		SMY 829R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D23001511MFCV	Excess (\$)		0.00	
	Assign From	CAROLINE CABRERA	Assign Date		03/05/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO 1.6 (A)	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	KNAF3416MM5097686	Colour		GREY	
	Odometer	24534 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	KUMHO		7 mm	
	L/H Front Tyre	205/55 R16	KUMHO		7 mm	
	R/H Rear Tyre	205/55 R16	KUMHO		7 mm	
	L/H Rear Tyre	205/55 R16	KUMHO		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/04/2023	Inspection Dat	е	04/05/2023	
	Survey held at	CYCLE & CARRIAGE KIA PTE L	_TD			
		330 UBI ROAD 3 (S) 408650				
5a.	Remarks					
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: