

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004533/KNY3Q2**Date:** 12/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00241362201

Claimant Vehicle No : SLC3322T **Insured Vehicle No :** SMV7792G

Date of Loss: 29/04/2023 Nature of Claim: TP Claim No: SNM23D203134/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC3322T**

Make & Model: KIA FORTE K3, 1.6 EX (A) Engine No: G4FGGH612306

Reg. Date: 11/05/2016 (Man. Year: 2016) Chassis No: KNAFX411MG5596341

Colour: Metallic Grey Odometer: 75767 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,510.60	1,033.60	2,477.00	70.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	680.00	1,320.00	66.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,510.60	1,713.60	3,797.00	68.90
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	5,510.60	1,350.00	4,160.60	75.50
+ GST 8.00/8.00% (S\$)	440.85	108.00	332.85	75.50
Nett Amount (S\$)	5,951.45	1,458.00	4,493.45	75.50

INSPECTION

Date of Assignment: 03/05/2023

Date Inspected: 03/05/2023 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2023)
Parts:	143	KIA FORTE K3 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC3322T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Repair	1,225.00 FL	*- FL
2	1		*FRONT DOOR GLASS O/S	Cut	662.00 FL	*452.00 FL
3	1		*FRONT DOOR WINDOW CHANNEL O/S	Serviceable	104.00 FL	*- FL
4	1		*FRONT DOOR WINDOW MOULDING O/S	Serviceable	65.00 FL	*- FL
5	1		*FRONT FENDER O/S	Repair	852.00 FL	*- FL
6	1		*WING MIRROR O/S	Cracked	485.00 FL	*485.00 FL
7	1		*WING MIRROR OUTER COVER O/S	Dented / Cut	226.00 FL	*142.00 FL
8	1		*WING MIRROR SIGNAL LAMP O/S	Serviceable	195.00 FL	*- FL
9	1		*WING MIRROR GLASS O/S	Broken	138.00 FL	*138.00 FL
10	10		*FRONT DOOR INNER TRIM BOARD CLIPS O/S	Not Necessary	55.00 FS	*- FS
11	1		*FRONT DOOR GLASS SOLAR FILM O/S	Necessary	200.00 FS	*60.00 FS
12	8		*FRONT FENDER COWLING CLIPS O/S	Not Necessary	44.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					4,301.00	1,277.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					790.40	243.40
Total Parts (\$\$)					3,510.60	1,033.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION .TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,000.00	400.00
2	TO DISCONNECT FRONT O/S DOOR WIRE HARNESS AND ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS OF POWER WINDOW	New	100.00	20.00
3	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	800.00	260.00
Gross Labour Cost (\$\$)			2,000.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >