

ASS. REC. BY:

REF:

08/11523004533/Twy 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 453K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Suelyn Vehicle: IN / OUTVeh No: XE8534 Yr Regn: 2015, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo FM370 C.C. 10837Colour: orange/white A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV2XIE1AIFB 733824

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 315/80R22.5R: ~ ~ (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. _____ D.O.I. 5/5/23Survey held at ASUN Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.I. (%) _____

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424

Main Line: 6265 0980 Fax: 6265 6068

Email: enquiry@asmauto.com.sg

Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

DATE : 03.05.2023

TO : Allianz Insurance Singapore Pte. Ltd.
ATTN : Motor Claim Department
TEL. NO. : 6714 3369
EMAIL : claims@allianz.com.sg

VEHICLE NO. : XE 853 U
MODEL NO. : VOLVO FM370 42T RSS SC
CHASSIS NO. : YV2X1E1A1FB733824
ENGINE NO. : D11356769 (10837 cc)
LTA REG DATE : 14.07.2015 - 13.07.2025

CC : Masindo Logistics Pte. Ltd.

CLAIM TYPE : Own Damaged
D.O.A : 25.04.2023
CLAIM REF NO. : asm/AC23051/JL

Quotation for Accident Repair

S/N	SPARE PARTS	QTY	UOM
1	Front windscreen <i>crd</i> ✓	1	pc
2	Front windscreen sealing <i>rel</i> ✓	1	pc
3	Wiper garnish, center <i>?</i>	1	pc
4	Wiper garnish, RH <i>crd</i> ✓	1	pc
5	Front upper panel <i>bt</i> ✓	1	unit
6	Front panel top garnish (silver) <i>crd</i> ✓	1	pc
7	Front panel top grille, center <i>?</i>	1	pc
8	Front panel top grille, RH <i>mis</i> ✓	1	pc
9	Front panel lower grille <i>crd</i> ✓	1	pc
10	Front panel lower grille mesh <i>crd</i> ✓	1	pc
11	Emblem "Volvo" <i>de</i> ✓	1	set
12	Front panel lock, RH <i>?</i>	1	pc
13	Lock bracket, RH <i>?</i>	1	pc
14	Front panel absorber (gas spring), LH & RH <i>?</i>	2	pcs
15	Firewall <i>?</i>	1	unit
16	Firewall cross member <i>?</i>	1	unit
17	Cross member grille <i>?</i>	1	pc
18	Anti-roll bar <i>X</i>	1	unit
19	Bearing housing, anti-roll bar <i>X</i>	2	pcs
20	Anchorage (cabin bracket), RH <i>?</i>	1	pc
21	Front cabin shock absorber, RH <i>?</i>	1	pc
22	Front lower panel w/top grille <i>crd</i> ✓	1	pc
23	Lower panel bracket, RH <i>?</i>	1	pc
24	Lower panel bottom step <i>?</i>	1	pc
25	Lower panel bottom step hinges, LH & RH <i>?</i>	2	pcs
26	Headlamp assy, RH <i>crd</i> ✓	1	pc
27	Headlamp control unit, RH <i>?</i>	1	pc
28	Side indicator lamp assy, RH <i>crd</i> ✓	1	pc
29	Headlamp panel, RH <i>crd</i> ✓	1	pc
30	Headlamp panel cover, RH <i>mis</i> ✓	1	pc
31	Headlamp inner frame, RH <i>?</i>	1	pc
32	Foglamp cover, RH <i>mis</i> ✓	1	pc
33	Concealing panel, RH <i>crd</i> ✓	1	pc
34	Underrun guard <i>bt</i> ✓	1	unit
35	Underrun guard bracket, RH <i>bt</i> ✓	1	pc
36	Front bumper, RH <i>mis</i> ✓	1	pc
37	Mirror arm assy, RH <i>bus</i> ✓	1	pc
38	Side mirror glass, RH - top <i>X</i>	1	pc



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424

Main Line: 6265 0980 Fax: 6265 6068

Email: enquiry@asmauto.com.sg

Co. / GST Reg. No.: 201203813C

bizSAFE₃

39	Side mirror back cover, RH - top ✓	1	pc
40	Side mirror glass, RH - bottom <i>cut</i>	1	pc
41	Side mirror back cover, RH - bottom <i>cut</i>	1	pc
42	Door panel, RH <i>bt</i>	1	unit
43	Door trim panel, RH ?	1	pc
44	Foot board, upper RH <i>eng</i>	1	pc
45	Foot board bracket, RH ?	1	pc
46	Foot step, upper RH ✓	1	pc
47	Foot step, lower RH ✓	1	pc
48	Foot board, lower RH <i>cut</i>	1	pc
49	Foot board support, lower RH <i>bt</i>	1	pc

S/N

LABOUR CHARGES

- 1 Remove and replace faulty parts, jacking, straightening and welding etc.
- 2 Spray painting
- 3 Towing fee

GRAND TOTAL : \$ 16,000.00

Taufik 97495749

No 7 Antwise Ex 91500

L/S Resurvey after repair

taufik @ 1kauto.com

5/5/23 @ 220 pm

10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: