

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23004537/UNY3M4**Date:** 12/05/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1002493929

**Claimant Vehicle No :** SKV8761M**Insured Vehicle No :** SLW241H

Date of Loss: 26/04/2023

Nature of Claim: TP

Claim No: 312084

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKV8761M**

Make &amp; Model: TOYOTA WISH, 1.8 X CVT ABS D/AIRBAG 2WD 5DR (A)

Engine No: 2ZR1589617

Reg. Date: 06/10/2015 (Man. Year: 2015)

Chassis No: ZGE206024361

Colour: Silver

Odometer: 134541 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,412.95	2,474.62	1,938.33	43.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,180.00	2,500.00	67.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,092.95</b>	<b>3,654.62</b>	<b>4,438.33</b>	<b>54.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
<b>(S\$)</b>	8,092.95	2,900.00	5,192.95	64.17
<b>+ GST 8.00/8.00% (S\$)</b>	647.44	232.00	415.44	64.17
<b>Nett Amount (S\$)</b>	<b>8,740.39</b>	<b>3,132.00</b>	<b>5,608.39</b>	<b>64.17</b>

INSPECTION

Date of Assignment: 04/05/2023

Date Inspected: 08/05/2023

Inspected At:

Z-ONE AUTOMOTIVE PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-87 AUTOBAY@KAKI BUKIT  
SINGAPORE 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV8761M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	1,060.70 FL	*- FL
2	2		*FRONT BONNET HINGES L/R	Not Necessary	127.40 FL	*- FL
3	1		*FRONT BONNET INSULATOR	Not Necessary	445.00 FL	*- FL
4	1		*FRONT BUMPER	Dented	639.70 FL	*639.70 FL
5	1		*FRONT BUMPER FOG LAMP COVER LH	Scratched	92.40 FL	*92.40 FL
6	1		*FRONT BUMPER INNER SPONGE	Torn	110.60 FL	*110.60 FL
7	1		*FRONT BUMPER RADIATOR GRILLE (BLACK & CHROME)	Not Necessary	449.30 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Repair	330.60 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Cracked/ O/S Not Necessary	136.20 FL	*68.10 FL
10	1		*FRONT FENDER LH	Dented/Bent	1,071.80 FL	*1,071.80 FL
11	1		*FRONT HEADLAMP LH	Scratched/Cracked	1,050.10 FL	*1,050.10 FL
12	1		*FRONT RADIATOR LOWER GRILLE LH	Not Necessary	50.00 FL	*- FL
13	1		*FRONT FENDER INNERSHIELD N/S	Deformed/Torn	186.80 FL	*186.80 FL
14	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
15	1		*SET FRONT FENDER INNER SHIELD CLIP (N/S)	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,850.60	3,279.50
- List Item Discount on L Items 25.00/25.00% (S\$)	1,437.65	804.88
Total Parts (S\$)	4,412.95	2,474.62

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSNG. (TO FR)	New	150.00	20.00
2	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUCNTIONING	New	150.00	0.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	680.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,700.00	450.00
5	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL	New	180.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,680.00</b>	<b>1,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >