

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURANCE BHD		Ref:	CS3/LPC23004538/Rqy3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	11/05/2023	
			Code	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBB 2407M	Veh. Inspected	XD 4695M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	22/23/23/VC05/027344	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	04/05/2023	
2. Vehicle Particulars & Condition					
	Make & Model	HINO FS1ELKD	c.c	12913	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	JHDFS1ELKXXX10243	Colour	BLUE	
	Odometer	793933 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
	L/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
	R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
	L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FR			
5.	General Information				
	Accident Date	01/05/2023	Inspect Date / Time	04/05/2023 (03:47 PM)	
	Survey held at	REDANTS ENGINEERING			
		10 BUROH STREET #04-26/29 WEST CONNECT BUILDING SINGAPORE 627564			
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC23004538/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser