5/29/23, 10:31 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III23004540/KQY3M4

Date: 29/05/2023

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747_02

Claimant Vehicle SMC9446T Insured Vehicle No: SNJ2785L

No:

Date of Loss: 28/04/2023 Nature of Claim: TP Claim No: MFL2023D0004857

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC9446T

Make & Model: HYUNDAI ACCENT (RB), 1.4 CVT (A) Engine No: G4LCJU022883

Reg. Date: 30/07/2018 (Man. Year: 2018) Chassis No: KMHCU41BTKU440122

Colour: Metallic Grey Odometer: 210964 km

Engine Capacity: 1368 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15
Front Left Side: Firenza 3 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Firenza 3 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
0.00	0.00	0.00	
0.00	0.00	0.00	
0.00	0.00	0.00	
0.00	0.00	0.00	
0.00	0.00	0.00	
0.00	0.00	0.00	
	4,800.00		
0.00	4,800.00	-4,800.00	
0.00	384.00	-384.00	
0.00	5,184.00	-5,184.00	
	0.00 0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 4,800.00 0.00 4,800.00 0.00 384.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 4,800.00 -4,800.00 0.00 384.00 -384.00

INSPECTION

Date Inspected:

Date of Assignment: 04/05/2023

S Three Automotive Recovery Pte Ltd (HQ)

Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector

С

Singapore 575643

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

04/05/2023 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 May 2023)

Parts: 143 HYUNDAI ACCENT (RB) 1.4 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC9446T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

5/29/23, 10:31 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >